

PROCESSING OPERATIONS CONTROL OMI PLANNING SHEET



PG 0 01

Wad Number S6444-J01-R02	SITE LCC	Elem CD V	End Item 103 FLT: 030	DATE: 08/09/2001 TIME: 18:53:36
Title: SSV ICE AND DEBRIS ASSESSMENT				Sub Element/Zone 30
Project Work Order No.	Hazard: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	SFOC Safety <i>NA Total Risk</i>	<input checked="" type="checkbox"/> Local Copy <input checked="" type="checkbox"/> Firing Room Copy	
Authorizing Document ORB330	Material & Equipment: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	MICR Req'd <input type="checkbox"/> Yes <input type="checkbox"/> No	OMRS: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	

PERFORM THE FOLLOWING:

Pre-Ops Setups

Task	Operation Number	Seq	Steps
------	------------------	-----	-------

Task	Operation Number	Seq	Steps
CVAS	TIPS	ME	TACCS
USA VM 002	N/A	USA VM 093	USA VM 014

OPS Support

Task	Operation Number	Seq	Steps	Task	Operation Number	Seq	Steps
------	------------------	-----	-------	------	------------------	-----	-------

Operating Instructions

Task	Seq	Steps	Task	Seq	Steps
	010			090	
	020			100	
	030			110	
	040			120	
	050			130	
	060			140	
	070			150	
	080				

Post Ops

Task	Operation Number	Seq	Steps
------	------------------	-----	-------

Appendices

Task	Seq
N/A	

Subtask WAD's

N/A

Planner <i>A. McCord</i>	Ext <i>6523</i>	QC Closure <i>[Signature]</i>	Date <i>8-5-01</i>	Page 1 OF 1
-----------------------------	--------------------	----------------------------------	-----------------------	----------------

OMI TASK CLOSEOUT CHECKLIST

OMI No. <u>2444</u>	Run No. <u>Rev. 5-01 Run 2</u>	Task Control No. (TCN) <u>2115373</u>
Start Date <u>8/9/01</u>	Completion Date <u>8/31/01</u>	Closure Date <u>8/31/01</u>

	QC/Eng.	Date
1. Deviation Index: Verify total number of deviations agree with index. Verify entry is correct into OMI.	<u>[Signature]</u>	<u>8/31/01</u>
2. Constraints List: Verify all constraints are accepted by QC or waived by Engineering. Verify that constraints list is complete and closed. <u>Subtask to 5007 R. Seal EIM</u>	<u>N/A</u>	<u>N/A</u>
3. IPR's: Verify that all IPR's are closed or upgraded to problem reports or dispositioned as no constraint to OMI closure and incorporated in central IPR system and a copy of the central IPR sort attached.		
4. Verify that material and equipment requirement list enclosed (if applicable).	<u>N/A</u>	<u>N/A</u>
5. OMI: Verify that all pages or verification sheets are completed, stamped, and dated in the lower left/right hand corners.		<u>8/31/01</u>
6. OMI: Verify that all miscellaneous documents/procedures have sequence number referenced and stamped; e.g., photos, sample results, etc.		<u>8/31/01</u>
7. Planned task/OMI satisfactorily completed. OPR: <u>X. Seal EIM</u> <u>8/31/01</u>		<u>8/31/01</u>
8. LSS review prior to closure for CIL OMI's. MMC <u>N/A</u> Thiokol <u>N/A</u>		

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

SSV ICE AND DEBRIS ASSESSMENT

Element/End Item: **ALL**
Flow/Usage: **ET-103 & SUBS**
Facility: **LC 39**
Design Center Concurrence: **MSFC/JSC**
Category: **B**
OPR: **ETM**
TTL ORG: **SE**

**This document contains
HAZARDOUS operations.**

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table of Contents:

1.0 INFORMATION.....	1
1.1 Objective.....	1
1.2 Special Instructions All Operations.....	2
1.3 Operations List.....	4
2.0 SAFETY INFORMATION.....	5
2.1 Hazards.....	5
2.2 Safety Requirements.....	5
2.4 Reference Safety Documentation.....	5
3.0 STAGING REQUIREMENTS.....	6
3.1 Referenced Engineering Documentation.....	6
3.1.2 Documents.....	6
3.2 Parts, Materials, Equipment, and Special Tools.....	6
3.2.8 Personal Protective Equipment.....	6
4.0 PLANNING REQUIREMENTS.....	7
4.3 LPS Requirements.....	7
4.3.1 Computer Systems.....	7
4.4 Support Services, Commodities, and Equipment.....	8
4.4.2 Communications.....	8
4.4.3 OTV.....	8
4.4.4 Countdown Display/Status.....	9
4.4.8 Services.....	9
4.4.12 Propellants, Gases and Chemicals.....	9
5.0 CONFIGURATION ACCOUNTING AND VERIFICATION.....	10
5.1 Specific OMRS Requirements Satisfied by this TOP.....	10
5.5 List of References.....	11

1.0 INFORMATION

1.1 Objective

Provide necessary tasks that document, monitor and evaluate ice and debris conditions to eliminate or minimize debris concerns of the integrated SSV during ET tanking, FRF, launch, and associated detanking.

Description

1. This OMI is performed as subtask to S0007/S0014/S0037.
2. This OMI provides documentation of ice/debris activities:
 - A. Pre-launch icing briefing
 - B. Pre-launch debris inspection
 - C. Countdown - Based timeline evaluation monitoring of ET TPS surfaces using OTV
 - D. OTV monitoring of seal/flange areas for cryogenic leakage
 - E. SSV OTV monitoring for debris conditions during countdown
 - F. Cryogenic replenish inspection for evaluation of SSV and facility debris concerns or anomalies
 - G. Evaluation of concerns/anomalies in the event of ET detanking
 - H. Review of engineering film data for SSME ignition, launch, ascent, ET separation, and orbiter landing.
3. Orbiter landing debris information is contained in the NASA publication for Ice and Debris Assessment. That report is referenced in this OMI for continuity of debris data.

1.2 Special Instructions All Operations

1. This OMI is run as a subtask to OMI's S0007, S0014, and S0037. All PAD clearing and controlled access operations will be performed per those OMI's.
2. Constraints will be statused by controlling OMI's S0007/S0014/S0037.
3. The OTV camera numbering scheme for PAD A/B is 0XX/1XX.
4. Task Team Leader assignment: NASA PH-H is TTL for L-20 Hour Walkdown, Final Inspection, and Post Launch/Drain Walkdown. ETM is TTL for all other operations.
5. From time stable replenish mode starts until start of final SCAN, scanning with individual cameras should be performed approximately once per hour.
6. Cameras 061/161, 063/163, and 070/170 may be released to NASA select with CICE concurrence.
7. All personnel participating in final inspection and post drain walkdown shall be current in following training:
 - A. Emergency PAD egress
 - B. Fire fighting
 - C. ELSA
8. Milestones:
 - A. MLP portion of post launch walkdown commences at approximately T + 1 hours.
 - B. PAD acreage portion of the post launch walkdown commences at approximately T + 2 hours. (may be deferred until preferred daylight hours.)
 - C. Post drain walkdown commences at approximately T + 4 hours after drain initiated (typically 1 1/2 hours after LH₂/LO₂ low level sensors dry).
9. Hands-on investigation required for all ET-TPS defects suspected of violating NSTS 08303 ice/debris inspection criteria.

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

10. From time launch scrub is declared until 1.5 hours past time LH₂/LO₂ low level sensors read dry, OTV camera scanning shall be performed approximately once per hour.
11. OTV cameras 004/104, 009/109, 013/113, 033/133, 042/142, 054/154, 055/155, 056/156, 060/160, 061/161, 062/162, 063/163, 064/164, 065/165, 066/166, 067/167, 068/168, 069/169, 070/170, and 071/171 shall be used to monitor LO₂/LH₂ tank drain operations.
12. Excessive vapors are defined as being more severe than that described in NSTS 08303 - Ice/Debris Inspection Criteria or NSTS 16007 - Launch Commit Criteria - Hazardous Gas Subsystem.
13. Quality coverage is not required for performance of this OMI. Ref SFOC-GO0007. Ice and Debris Team Operations are exempt from quality coverage. The ROR (CTIF) performs the CMQC function for all non-hazardous operations.
14. Personnel using Sony DKC-ID1 camera shall verify lithium ion battery is securely locked in the bayonet fitting and the lithium button battery door is securely locked and taped in place.
15. Verify camera flash is deactivated.
16. Personnel using Kodak DC 50/120 camera shall verify alkaline batteries are properly installed.
17. Personnel using digital cameras shall not operate in H₂ leak or O₂ rich environment (23 percent or greater).
18. Personnel using the Sony MVC-FD91 camera shall verify the lithium ion battery is securely locked and the battery door is locked closed. Personnel shall verify that both battery doors (lithium ion and lithium button) are closed and taped shut.
19. Personnel shall verify that cameras and equipment are securely tethered when at the PAD while the SSV is present.

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

1.3 Operations List

Operation		Shop/ Cntl Rm Console	OPR	Haz (Y/N)	Duration (Hrs)
No.	Title				
10	Support Preparations	STM/ FR2	ETM	N	0.2
20	Ice Prediction Briefing	SE/ NA	ETM	N	0.5
30	Pre-launch Walkdown	SE/ NA	ETM	N	2.0
40	Ice Frost Debris Console Initial Configuration Setup	SE/ FR2	ETM	N	3.0
50	SSV Debris Assessment	SE/ FR2	ETM	N	18.0
60	Group 1 Monitoring LO2 Chill Down Thru T-0	SE/ FR2	ETM	N	15.0
70	Group 2 Monitoring - LH2 Chill Down Thru T-0	SE/ FR2	ETM	N	15.0
80	Final Inspection	SE/ FR2	ETM	Y	3.0
90	LO2/LH2 Drain Monitoring	SE/ FR2	ETM	N	4.0
100	Console Securing	SE/ FR2	ETM	N	0.5
110	Summary Tape	SE/ FR2	ETM	N	18.0
120	Post Drain Walkdown	SE/ NA	ETM	Y	2.0
130	Post Launch Walkdown	SE/ NA	ETM	Y	3.0
140	Film Review	SE/ NA	ETM	N	15.0
150	Final Report	SE/ NA	ETM	N	0.5

2.0 SAFETY INFORMATION

2.1 Hazards

Operation

1. Working at unprotected heights.
2. Walkdown at PAD while SSV is in stable replenish mode.

2.2 Safety Requirements

Operation

1. If lightning activity is forecast to be within 5 miles of launch PAD, CTC and SFOC safety shall implement provisions of adverse/severe weather and lightning policy contained in GSOP 5400 Ground Safety Operations Procedures.
2. There are no safing/shutdown or evacuation steps required in this OMI.
3. Hazardous operations within this subtask OMI will not be started until safety concurrence to proceed has been given per the integrated OMI controlling this subtask.

2.4 Reference Safety Documentation

Number	Rev	Title
KHB 1710.2	LI	KSC Safety Practices Handbook
GSOP 5400	LI	Ground Safety Operating Procedure

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

3.0 STAGING REQUIREMENTS

3.1 Referenced Engineering Documentation

3.1.2 Documents

OPERATION 120

Document No.	Rev	Title
NSTS 08303	(LI)	NSTS PROGRAM ICE/DEBRIS INSPECTION CRITERIA

3.2 Parts, Materials, Equipment, and Special Tools

3.2.8 Personal Protective Equipment

OPERATION 30	Nomenclature safety harness lanyard
OPERATION 80	Nomenclature safety harness lanyard Nomex coveralls with gloves and hoods ELSA
OPERATION 120	Nomenclature safety harness lanyard hardhats flame retardant coveralls
OPERATION 130	Nomenclature safety harness lanyard hardhats flame retardant coveralls

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

4.0 PLANNING REQUIREMENTS

OIR Required Yes [], No [X]

4.3 LPS Requirements

4.3.1 Computer Systems

PC GOAL
CCMS Configuration
CDS
CMS

GSE Links/HIMs

Link	FEP	Location	HIM	Octal Addr	Function
------	-----	----------	-----	------------	----------

DPS Configuration

OPS Mode - ____
Dedicated DEU/DDU - ____

Vehicle Links and Formats

Link	FEP	Freq	Downlink	Downlist
------	-----	------	----------	----------

Control Room Consoles Required

SDC/RTIF Configuration

RPS Configuration

Link	Freq	Element	Downlink Format
------	------	---------	-----------------

ESA monitors/hot spares

CCS Configuration

Link	FEP	Location	HIM	Octal Addr	Function
------	-----	----------	-----	------------	----------

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

CCS Consoles Required

4.4 Support Services, Commodities, and Equipment

4.4.2 Communications

(Per controlling OMI S0007, S0014 or S0037)

Voice Recording:

Radio nets:

Paging:

Area warning:

Portable radios (loan pool):

Type	Qty	Net/Freq	Record	Duration/Purpose
------	-----	----------	--------	------------------

Portable OIS units:

Special communications:

4.4.3 OTV

(Per controlling OMI S0007, S0014 or S0037)

OTV Cameras required: 004/104, 009/109, 013/113, 033/133, 042/142, 054/154, 055/155, 056/156, 060/160, 061/161, 062/162, 063/163, 064/164, 065/165, 066/166, 067/167, 068/168, 069/169, 070/170, and 071/171

OTV Cameras to be recorded: 004/104, 009/109, 013/113, 033/133, 042/142, 054/154, 055/155, 056/156, 060/160, 061/161, 062/162, 063/163, 064/164, 065/165, 066/166, 067/167, 068/168, 069/169, 070/170, and 071/171

OTV Monitor:

Special OTV requirements:

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

4.4.4 Countdown Display/Status

<u>Display Required</u>	<u>Bldg</u>	<u>Room</u>	<u>Operation Time</u>
Timing	LCC	FR2	Duration of Test
Countdown and GMT	LCC	FR2	Duration of Test

4.4.8 Services

<u>Service/Special Requirements</u>	<u>Location</u>	<u>Purpose</u>
SHOC Safety	LC-39 A&B	Safety Support
ALSA'S (3)	LC-39 A&B	Inspection Team Use
Radio Net 105	LC-39 A&B	Inspection Team Use

4.4.12 Propellants, Gases and Chemicals

<u>Commodity</u>	<u>Spec No.</u>	<u>Quantity</u>	<u>Rcvr</u>	<u>Location</u>	<u>Minimum Press</u>	<u>Delivery Time</u>
LN ₂	SES-0073 -6.3-5	Min 750 Cu ft	PH-H 861-3648	Pad 39B Camera Site 2	3000 PSI	1 week prior to T-0

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

5.0 CONFIGURATION ACCOUNTING AND VERIFICATION

5.1 Specific OMRS Requirements Satisfied by this TOP

OMRS NO.	NOMENCLATURE/ EFFECTIVITY	SEQ-STEP (CAP)
S00000.001	BT TPS MON DURING DETANK TAF/C	20-005
S00000.001	POST DETANK BT TPS INSPECT TAF/C	120-002
S00000.001	PRELAUNCH WEATHER BRIEFING (L-1 DAY) VAFI-FC	20-001
S00000.002 (1)	BT TPS SURFACE MONITORING T23, 27-29, 31-333	60-012 70-012
S00000.002 (1)	MONITOR SOL VENT HORN VAFI-FC	50-021
S00000.001 (1)	MONITOR BT ORB MPS FOR LEAKAGE VAFI-FC	70-012
S00000.001	HIGH WIND BT NOSE INSPECTION SAF/C	50-016 60-012
S00000.001 (1)	POST LAUNCH SHUTTLE PAD AREA INSPECTION SAFI-999	130-002
S00000.001 (1)	ENG REVIEW & ANALYSIS OF LAUNCH FILM SAFI-999	150-002
S00000.001-A (1)	AN ENGINEERING PAD INSPECTION TEAM SAFI-999	50-002
S00000.001-B (1)	INSPECT ORBITER AFT ENGINE SAFI-999	60-002
S00000.001-C (1)	INFRARED SURVEILLANCE SAFI-999	80-002
S00000.001 (1)	PRELAUNCH SHUTTLE/PAD AREA INSPECTION SAFI-999	30-001

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

5.5 List of References

OPERATION 20

Reference No.	Rev	Title
NSTS 16007	(LI)	NSTS Program Launch Commit Criteria - Hazardous Gas Subsystem and Appendix F

OPERATION 30

Reference No.	Rev	Title
80901019010	(LI)	ET Post Build Acceptance and In-Process Rework Requirements Manual - Offsite

OPERATION 40

Reference No.	Rev	Title
79K24576	(LI)	OTV System Installation, LC 39, Pad A
79K24522	(LI)	OTV System Installation, LC 39, Pad B

OPERATION 50

Reference No.	Rev	Title
SPI SP-519	(LI)	OMI and OM Implementation
SFOC GO0007	(LI)	Quality Planning Requirements Document (QPRD)

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

OPERATION 10 Support Preparations

Shop: STM

Cntrl Rm Console: FR2

OPR: ETM

Zone: NA

Hazard (Y/N): N

Duration (Hrs): 0.2

10-1 STM JYVO 138

Verify PAD OTV system is configured to support S6444 as scheduled.

Support: COMM

10-2 STM JSTC 111
JSTC *SCB 114

Verify eight 10-minute ELSA's available at complex J for use by Final Inspection Team (ref S0007/S0014/S0037).


Support: LS

10-3 STM TBC 136


Operation - Support Preparations complete.

*** End of Operation 10 ***

WC
0-3
USA
SEP 8 1991



ET
01
2/7/91



WC 013 USA
 * 100 8 01
 EXTENDED
 ON 10/10/01
 10/10/01

& VOD 2 pl.
 ETE A. S. e.

ET
 01 8/9/01

ET
 01

8/9/01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

OPERATION 20 Ice Prediction Briefing

Shop: SE
Cntrl Rm Console: NA
OPR: ETM
Zone: NA
Hazard (Y/N): N
Duration (Hrs): 0.5

NOTE

Ref: NSTS 16007 (LI) NSTS Program Launch Commit Criteria - Hazardous Gas Subsystem and Appendix F defines the ET No-Ice Zone.

20-1 CICE

Conduct L-1 day ice prediction briefing with launch director.

PH-H Signature

[Handwritten Signature] 8/10/01
ARANDU CLIN

OMRSD S00FA0.900

8/10/01

20-2 Operation - Ice Prediction Briefing complete.

*** End of Operation 20 ***

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

OPERATION 30 Pre-launch Walkdown

Shop: SE
Cntrl Rm Console: NA
OPR: ETM
Zone: PAD
Hazard (Y/N): N
Duration (Hrs): 2.0

WARNING

Personnel working at heights greater than 4 feet and within 6 feet of an unguarded edge shall wear a **safety harness** with a **lanyard** secured to an approved tie off point, substantial structural member (no handrails) or a properly installed life line.

NOTE

This operation is performed at approximately L-20 hours. When this operation is performed in support of a 24 hour scrub turnaround, the preceding launch scrub post drain walkdown and this pre-launch walkdown may be performed concurrently.

Inspections may also be performed from the RSS, GO₂ Vent Arm (GVA), -Y OWP, or +Y OWP if still extended and accessible.

Ref: 80901019010 (LI) ET Post Build Acceptance and In-Process Rework Requirements Manual - Offsite

NASA ET Mechanical Engineer (PH-H) or designee shall function as team leader. Following personnel are optional walkdown participants.

NASA Engr	(4)
SFOC Engr	(2)
LMSSC - LSS	(1)
Boeing - LSS	(1)
SRB ELE	(1)
Thiokol - LSS	(1)

30-1 Debris inspection team **perform** walkdown of SSV and MLP per following:

1. Team leader **verify** S6444 pre-test briefing complete.
2. **Assemble** following essential personnel

NASA PH-H Engineering - 1
SFOC ETM Engineering - 1
3. **Inspect** following areas (as a minimum) from the MLP, RSS and FSS to identify/ resolve potential debris sources.

Areas to be inspected

A. Launch vehicle external surfaces

- Orbiter
- SRB s
- External Tank

B. MLP surfaces

- LH and RH SRB holddown posts
- Deck including deck bolts, fixtures, and edge gutters
- SSME LH and RH SRB exhaust openings, and sound suppression (SS) troughs
- TSM's and camera housings

4. Ref Table 30-1, **document** and SIM Photograph SSV and Launch PAD Configuration.

Description: Pre launch walkdown.

OMRSD S00U00.030-1

110
VIA
USA

8/9/01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

- 30-2 **Record** all facility discrepancies in S0007. Submit copy to PAD leader and notify TBC/CTC. **Verify** no constraints to continue.

PH-H *[Signature]* Date 8/9/01
RICHARDS
ETM *[Signature]* Date 8/9/01
RIVERA

- 30-3 Operation - Pre-launch Walkdown complete.

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 30-1 Photo Requirements for SSV and Launch Pad Configuration

Photos from MLP			
<u>Photo</u>	<u>Camera Orientation</u>	<u>Lens</u>	<u>Notes</u>
ET -Z	Vertical	28 mm	
Aft Dome	Horizontal	28 mm	
Aft Dome	Horizontal	35-70 mm	
LH SRB from North	Horizontal	35-70 mm	All water troughs in view
LH SRB from North	Vertical	35-70 mm	3-4 water troughs in view
LH SRB from East	Vertical	35-70 mm	
RH SRB from North	Horizontal	35-70 mm	All water troughs in view
RH SRB from North	Vertical	35-70 mm	3-4 water troughs in view
RH SRB from West	Vertical	35-70 mm	
SRB Heater Elec T-0	Horizontal	35-70 mm	Foam intrusion: May need flash
North HDP	Vertical	35-70 mm	Representative view
South HDP	Vertical	35-70 mm	Representative view
TSM T-0 LH ₂	Vertical	35-70 mm	Flash needed
TSM T-0 LO ₂	Vertical	35-70 mm	Flash needed
Orbiter Left & Right Wing	Vertical	35-70 mm	From below ET (1 Photo each wing)

ET
01

3/9/01

Nov 12

Feb 24 1960

THE BEST OF BOTH WORLDS

14. Casey Adams 10/1/14

L. L. M. V. K. K. K. K.

1st 2nd 3rd 4th 5th 6th 7th 8th 9th 10th 11th 12th 13th 14th 15th 16th 17th 18th 19th 20th 21st 22nd 23rd 24th 25th 26th 27th 28th 29th 30th 31st 32nd 33rd 34th 35th 36th 37th 38th 39th 40th 41st 42nd 43rd 44th 45th 46th 47th 48th 49th 50th 51st 52nd 53rd 54th 55th 56th 57th 58th 59th 60th 61st 62nd 63rd 64th 65th 66th 67th 68th 69th 70th 71st 72nd 73rd 74th 75th 76th 77th 78th 79th 80th 81st 82nd 83rd 84th 85th 86th 87th 88th 89th 90th 91st 92nd 93rd 94th 95th 96th 97th 98th 99th 100th 101st 102nd 103rd 104th 105th 106th 107th 108th 109th 110th 111th 112th 113th 114th 115th 116th 117th 118th 119th 120th 121st 122nd 123rd 124th 125th 126th 127th 128th 129th 130th 131st 132nd 133rd 134th 135th 136th 137th 138th 139th 140th 141st 142nd 143rd 144th 145th 146th 147th 148th 149th 150th 151st 152nd 153rd 154th 155th 156th 157th 158th 159th 160th 161st 162nd 163rd 164th 165th 166th 167th 168th 169th 170th 171st 172nd 173rd 174th 175th 176th 177th 178th 179th 180th 181st 182nd 183rd 184th 185th 186th 187th 188th 189th 190th 191st 192nd 193rd 194th 195th 196th 197th 198th 199th 200th 201st 202nd 203rd 204th 205th 206th 207th 208th 209th 210th 211th 212th 213th 214th 215th 216th 217th 218th 219th 220th 221st 222nd 223rd 224th 225th 226th 227th 228th 229th 230th 231st 232nd 233rd 234th 235th 236th 237th 238th 239th 240th 241st 242nd 243rd 244th 245th 246th 247th 248th 249th 250th 251st 252nd 253rd 254th 255th 256th 257th 258th 259th 260th 261st 262nd 263rd 264th 265th 266th 267th 268th 269th 270th 271st 272nd 273rd 274th 275th 276th 277th 278th 279th 280th 281st 282nd 283rd 284th 285th 286th 287th 288th 289th 290th 291st 292nd 293rd 294th 295th 296th 297th 298th 299th 300th 301st 302nd 303rd 304th 305th 306th 307th 308th 309th 310th 311th 312th 313th 314th 315th 316th 317th 318th 319th 320th 321st 322nd 323rd 324th 325th 326th 327th 328th 329th 330th 331st 332nd 333rd 334th 335th 336th 337th 338th 339th 340th 341st 342nd 343rd 344th 345th 346th 347th 348th 349th 350th 351st 352nd 353rd 354th 355th 356th 357th 358th 359th 360th 361st 362nd 363rd 364th 365th 366th 367th 368th 369th 370th 371st 372nd 373rd 374th 375th 376th 377th 378th 379th 380th 381st 382nd 383rd 384th 385th 386th 387th 388th 389th 390th 391st 392nd 393rd 394th 395th 396th 397th 398th 399th 400th 401st 402nd 403rd 404th 405th 406th 407th 408th 409th 410th 411th 412th 413th 414th 415th 416th 417th 418th 419th 420th 421st 422nd 423rd 424th 425th 426th 427th 428th 429th 430th 431st 432nd 433rd 434th 435th 436th 437th 438th 439th 440th 441st 442nd 443rd 444th 445th 446th 447th 448th 449th 450th 451st 452nd 453rd 454th 455th 456th 457th 458th 459th 460th 461st 462nd 463rd 464th 465th 466th 467th 468th 469th 470th 471st 472nd 473rd 474th 475th 476th 477th 478th 479th 480th 481st 482nd 483rd 484th 485th 486th 487th 488th 489th 490th 491st 492nd 493rd 494th 495th 496th 497th 498th 499th 500th 501st 502nd 503rd 504th 505th 506th 507th 508th 509th 510th 511th 512th 513th 514th 515th 516th 517th 518th 519th 520th 521st 522nd 523rd 524th 525th 526th 527th 528th 529th 530th 531st 532nd 533rd 534th 535th 536th 537th 538th 539th 540th 541st 542nd 543rd 544th 545th 546th 547th 548th 549th 550th 551st 552nd 553rd 554th 555th 556th 557th 558th 559th 560th 561st 562nd 563rd 564th 565th 566th 567th 568th 569th 570th 571st 572nd 573rd 574th 575th 576th 577th 578th 579th 580th 581st 582nd 583rd 584th 585th 586th 587th 588th 589th 590th 591st 592nd 593rd 594th 595th 596th 597th 598th 599th 600th 601st 602nd 603rd 604th 605th 606th 607th 608th 609th 610th 611th 612th 613th 614th 615th 616th 617th 618th 619th 620th 621st 622nd 623rd 624th 625th 626th 627th 628th 629th 630th 631st 632nd 633rd 634th 635th 636th 637th 638th 639th 640th 641st 642nd 643rd 644th 645th 646th 647th 648th 649th 650th 651st 652nd 653rd 654th 655th 656th 657th 658th 659th 660th 661st 662nd 663rd 664th 665th 666th 667th 668th 669th 670th 671st 672nd 673rd 674th 675th 676th 677th 678th 679th 680th 681st 682nd 683rd 684th 685th 686th 687th 688th 689th 690th 691st 692nd 693rd 694th 695th 696th 697th 698th 699th 700th 701st 702nd 703rd 704th 705th 706th 707th 708th 709th 710th 711th 712th 713th 714th 715th 716th 717th 718th 719th 720th 721st 722nd 723rd 724th 725th 726th 727th 728th 729th 730th 731st 732nd 733rd 734th 735th 736th 737th 738th 739th 740th 741st 742nd 743rd 744th 745th 746th 747th 748th 749th 750th 751st 752nd 753rd 754th 755th 756th 757th 758th 759th 760th 761st 762nd 763rd 764th 765th 766th 767th 768th 769th 770th 771st 772nd 773rd 774th 775th 776th 777th 778th 779th 780th 781st 782nd 783rd 784th 785th 786th 787th 788th 789th 790th 791st 792nd 793rd 794th 795th 796th 797th 798th 799th 800th 801st 802nd 803rd 804th 805th 806th 807th 808th 809th 810th 811th 812th 813th 814th 815th 816th 817th 818th 819th 820th 821st 822nd 823rd 824th 825th 826th 827th 828th 829th 830th 831st 832nd 833rd 834th 835th 836th 837th 838th 839th 840th 84

lies

in
m

5 | 4 | 01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

135 Ft Level Photos

<u>Photo</u>	<u>Camera Orientation</u>	<u>Lens</u>	<u>Notes</u>
LO ₂ UMB	Vertical	35-70 mm	From OWP usually during T5401
LH ₂ UMB	Vertical	35-70 mm	From OWP usually during T5401

215 Ft Level Photos

<u>Photo</u>	<u>Camera Orientation</u>	<u>Lens</u>	<u>Notes</u>
ET surfaces from FSS	Vertical	35-70 mm	
LH SRB Frustrum and FWD skirt	Vertical	35-70 mm	
RH SRB Frustrum and FWD skirt	Vertical	35-70 mm	
Jack Pad C/O's	Horizontal	35-70 mm	Flash needed (1 each C/O)
LO ₂ Ogive Cable Tray	Vertical	35-70 mm	From RSS roof

255 Ft Level Photos

<u>Photo</u>	<u>Camera Orientation</u>	<u>Lens</u>	<u>Notes</u>
ET surfaces with GO ₂ vent ducts in view	Vertical	35-70 mm	
GO ₂ vent ducts	Horizontal	250 mm	

*** End of Table 30-2 Photo Requirements for SSV and Launch Pad Configuration

*** End of Operation 30 ***

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

OPERATION 40 Ice Frost Debris Console Initial Configuration Setup

Shop: SE
Cntrl Rm Console: FR2
OPR: ETM
Zone: NA
Hazard (Y/N): N
Duration (Hrs): 3.0

NOTE

The next step sets up the photo processing laptop for use in the Firing Room. This is not a constraint to set up of the console or to final inspection team operations. Network or equipment failures on the photo processing machine shall be annotated below.

- 40-1 Connect to KSC ground ops network and **configure** laptop computer to perform photo processing/ analysis.

Notes Ready for go

NOTE

The next step verifies the setup of the infrared scanners. This is not a constraint to set up of the ice console. IR scanner condition shall be annotated below.

- 40-2 Verify IR scanner operation condition, annotate below.

RSS: NOT OPERATIONAL

CS 2: OK

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

NOTE

The next step verifies the operation of console monitors in the Firing Room. This is not a constraint to set up of the console or to final inspection team operations. Equipment condition shall be annotated below.

40-3 Verify console condition by powering on monitors and tape recorders.

Monitors: OK

Tape recorders: OK

NOTE

ET OTV pre-mapping/initial position of cameras may be performed in random order.

Ref: 79K24576 (LI) OTV System Installation, LC 39, Pad A and

Ref: 79K24522 (LI) OTV System Installation, LC 39, Pad B define OTV camera locations.

FOV designates field-of view. RSS and -Y OWP must be retracted for completion of pre-mapping.

Pre-mapping steps/substeps in the remainder of this operation need not be performed if supporting a scrub turnaround and if performed during a previous run.

It is preferred to record all pre-mapping scanning on a single tape. However, multiple tapes may be used when lighting/ launch countdown constraints necessitate such.

01-15-2001
APPROVED

OMI S6444 J01
APPROVED


40-4 CVM1 JTV1 223

Perform OTV pre-mapping of External Tank exterior surfaces using OTV Cameras 004/104, 009/109, 013/113, 033/133, 042/142, 054/154, 055/155, 056/156, 060/160, 061/161, 062/162, 063/163, 064/164, 065/165, 066/166, and 067/167 as follows:

- **Insert** designated pre-map tape into trouble console VCR.
- **Punch-up** camera number on trouble monitor.
- **Start** recording on pre-map tape. **Record** start time (GMT).
- **Scan** from top-to-bottom, left-to-right and right-to-left at approximately full zoom-in.
- **Stop** recording on pre-map tape. **Record** stop time (GMT).
- **Record** data in Table 40-1.
- **Repeat** with each OTV camera listed until each has been used to scan the External Tank.
- **Remove** pre-map tape from trouble console VCR.

ETM _____

N/A
Date _____

Not Performed: 

8-10-01

40-5 CVM1 JTV1 223

Position OTV Cameras 004/104, 009/109, 013/113, 033/133, 042/142, 054/154, 055/155, 056/156, 060/160, 061/161, 062/162, 063/163, 064/164, 065/165, 066/166, 067/167, 070/170, and 071/171 to initial positions as defined in Table 40-2.


ETM _____

R Brewer
Date _____

Not Performed: *N/A*

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 40-1 ET Pre-Mapping Data		Tape #
OTV Camera	Start Time (GMT)	Stop Time (GMT)
004 / 104	 N/A	
009 / 109		
013 / 113		
033 / 133		
042 / 142		
054 / 154		
055 / 155		
056 / 156		
060 / 160		
061 / 161		
062 / 162		
063 / 163		
064 / 164		
065 / 165		
066 / 166		
067 / 167		

Notes:

N/A

Table 40-2 OTV Camera Initial Positions	
OTV Camera	Initial Position
004 / 104	FOV centered on GUCP
009 / 109	FOV on LH ₂ Umbilical including ET/Orbiter interface. Vary close-up and wide angle views with 063/163 and 064/164.
013 / 113	Full zoom in. View SW GO ₂ Vent Louver area.
033 / 133	FOV perpendicular to ET and with LO ₂ -to-Intertank splice at frame top and LH ₂ -to-Intertank splice at frame bottom. Then tilt down until XT2058 is in frame center.
042 / 142	FOV centered on Orbiter Access Arm-to-Orbiter interface.
054 / 154	FOV to encompass approximately 3 feet forward of XT2058 to 2 feet aft of XT2058. Orbiter wing and SRB should be in view at frame left.
055 / 155	Set FOV on north bridge LH ₂ pipeline flange.
056 / 156	FOV with LH ₂ Aft Dome in frame bottom and XT2058 in view at frame top.
060 / 160	Full zoom in. View SW GO ₂ Vent Louver area.
061 / 161	Full zoom-in. Adjust FOV until ET LO ₂ -to-Intertank splice is centered vertically and view is perpendicular to ET. Pan right until edge of the ET comes into view. Note: LO ₂ Tank may pass out-of-view.
062 / 162	Full zoom in. View NW GO ₂ Vent Louver area.
063 / 163	FOV on LH ₂ Umbilical including ET/Orbiter interface. Vary close-up and wide angle views with 009/109 and 064/164.
064 / 164	FOV on LH ₂ Umbilical including ET/Orbiter interface. Vary close-up and wide angle views with 009/109 and 063/163.
065 / 165	Full zoom out. Set FOV on aft part of ET with frame bottom approximately 2 feet below LH ₂ Aft Dome.
066 / 166	FOV perpendicular to ET with LO ₂ -to-Intertank splice at frame top. Then tilt down until Orbiter RH Wing/SRB intersection is in frame lower right.
067 / 167	Set FOV with LH ₂ Aft Dome toward frame bottom and 2 nd black ring of SRB in view.
070 / 170	Select down wind camera of these two as wide angle view of the SSV.
071 / 171	Set up wind camera for close-up view of SSME's.

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

40-6 Operation - Ice Frost Debris Console Initial Configuration Setup complete.

ETM Date 8/10/01

*** End of Operation 40 ***

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

OPERATION 50 SSV Debris Assessment

Shop: SE
Cntrl Rm Console: FR2
OPR: ETM
Zone: NA
Hazard (Y/N): N
Duration (Hrs): 18.0

NOTE

Steps in this operation are contingent upon progression of launch countdown operations and may not be performed if countdown is terminated.

Entire Operation Not Performed: N/A

NOTE

Until otherwise indicated, all times are referenced to S0007, S0014 or S0037 timelines.

No operations/steps within this subtask OMI may be performed as a stand-alone procedure. This OMI may only be performed as a subtask to S0007/S0014/S0037.

NOTE

Ref: SPI SP-519 (LI) OMI and OM Implementation and Ref: SFOC GO0007 (LI) Quality Planning Requirements Document (QPRD) . following step complies with requirements for ROR-as-CMQC function.

50-1

CTIF	TBC
TBC	CMQC 136

Notify TBC that CTIF will perform the CMQC function for STS 105, S6444 run 2. Request TBC notify CMQC that the ROR-as-CMQC option will be exercised for STS 105, S6444 run 2.

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

50-2

CTC	TBC	232
TBC	CTIF	136

Perform OTV and ice/frost monitoring area setups.

ETM R Brewer Date 8/10/07

50-3

CTIF	TBC	136
TBC	CTC	
CTC	STM	232

Verify Operation 10- Support Preparations complete.

ETM R Brewer Date 08/10/07

50-4

CTIF

Verify Operation 20 - Ice Prediction Briefing and Operation 30- Pre-launch Walkdown complete.

ETM R Brewer Date 8/10/07

8/10/07

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

50-5

CTIF CVM1 222
CVM1 222

Verify:

- All OTV cameras are on, tapes in recorder, and ready to commence OTV scanning, monitoring, and recording.
- Trouble tape recorder is ready.
- Ice Frost Debris Console Initial Configuration Setup complete.

ETM R Brewer Date 8/14/01

50-6

CTIF CICE 222
CVM1
CVM2
CIPC
CTIF JYVR 138
CVM1 JTV1 223
CVM2 JTV2 225

All personnel participating in OTV operations **report** test ready status.

ETM R Brewer Date 8/14/01

Support: COMM

5/13/01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

50-7

CTIF	TBC	136
TBC	CTC	232

Ice Frost Console Area Setups for OTV scanning complete.
Report readiness.


ETM N/A Date 8-16-01

Not Performed: 8-16-01

50-8

CTIF CVM1 222

From start of LO₂ chilldown until seal deflation/GO₂ vent hood retraction, **monitor** the +Y/-Y GO₂ vent seal-to-ET interface for seal fretting and continuous GO₂ escape.



OMRS 500FB0.350-1

ETM R. Brewer Date 08-16-01

Not Performed: N/A

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

NOTE

GO₂ vent seal fretting could induce damage to ET SOFL. Continuous GO₂ venting could result in formation of ice in the no ice zone (ref NSTS 16007). Ultimate decision to lift the vent hood rests with CMEC.

50-9

CTIF TBC 136
CMEC

If +Y/-Y GO₂ vent seal fretting or continuous GO₂ escape detected from start of LO₂ chilldown until seal deflation, **notify** CMEC for GO₂ vent hood removal.

ETM N/A Date N/A

Not Performed:

ME
08

8-10-01

50-10

CTIF CIPC 222

Monitor wind speed and direction from start of LO₂/LH₂ chill down through launch/scrub. CIPC **notify** CTIF if winds measured at 38 knots or greater from North +/-30 degrees as measured at 60 feet.

ETM

ME
08

 Date 8-10-01

Not Performed: N/A

WC
150
USA

Dev. 50
01 P

8/10/01
SEE DEV

50-5

8/10/01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

50-11

CTIF CVM1 222

Perform Operation 60 - Group 1 Monitoring.

ETM  Date 8-10-01

Not Performed: N/A

50-12

CTIF CVM2 222

Perform Operation 70- Group 2 Monitoring.

ETM  Date 8-10-01

Not Performed: N/A

50-13

CTIF CVM2 222

Once per hour minimum. after start of LO₂/LH₂ (until LO₂/LH₂ low level sensors read dry). scan LO₂ feed line brackets and flange closeouts per Table 50-1.

ETM  Date 8-10-01

Not Performed: N/A

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

50-14

CTIF CICE 222

As count proceeds, for concerns/ observations identified:

1. **Record** observation/concern on trouble tape per Table 50-1.
2. **Document** observed condition on Table 50-2, Observation Worksheet.

ETM  Date 8-10-01

Not Performed: N/A

50-15

TBC CTIF 136
CTIF CICE 222

Perform Operation 80 - Final Inspection when called by
S0007/S0014/S0037.

ETM  Date 8-10-01

Not Performed: N/A

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

NOTE

Final SSV scan typically commences at L-2 hours.

50-16

CTIF CVM1 222
CVM2

Perform final SSV scan.

ETM  Date 8-10-01

Not Performed: N/A

50-17

CTIF CVM1 222
CVM2

At start of T-9 minute hold, **configure** OTV cameras for terminal count.


ETM  Date 8-10-01

Not Performed: N/A

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

50-18



If winds are from the north (+/-30 degrees) and are 38 knots or greater: ^(PEAK AS MEASURED AT 60 FEET ABOVE GROUND) 60 FEET ABOVE GROUND) OR GREATER.

1. Monitor/videotape nose cone area during high winds.

2. Verify:

A. No ice formation on the +Y and -Y GO₂ vent seal footprint areas.

B. No damage to the ET TPS at the +Y and -Y GO₂ vent seal footprint areas.

C. No damage to the +Y and -Y GO₂ vent seals themselves.

D. No evidence of GO₂ leakage from +Y/-Y GO₂ vent seals to ET interface.

USA
VM
011

OMRSD S00L00.150

ETM N/A Date N/A

Not Performed: 8-10-01

50-19

CTIF


Verify launch or launch scrub (drain back). Record data.

Launch X Scrub N/A

Date 8-10-01 GMT Time 21:10 GMT

Scrub at T- N/A

ETM ME 08 Date 8-10-01



SEE DEV

50-9

8/10/01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

NOTE

When completely filled and drain is initiated, it takes approximately 1 hour until the LH₂ tank low level sensors read dry, and approximately 1.5 hours until the LO₂ tank low level sensors read dry.

50-20

CTIF CVM1 222
CVM2

If launch scrubbed (or drain back declared) after start of LO₂/LH₂ slow fill mode:

- **Perform** Operation 90 - LO₂/LH₂ Drain Monitoring.
- **Record** observations/concerns on trouble tape per Table 50-1.
- **Document** all observations/concerns on Table 50-2 Observation Worksheet.

ETM N/A Date N/A

Not Performed:

ME
08

8-10-01

50-21 CTIF

GO₂ Vent seal to ET interface monitoring for seal fretting and continuous GO₂ escape complete.

OMRSD S00FB0.350-1

ETM

ME
08

 Date 8-10-01

Not Performed: N/A

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

50-22

CTIF CVM1 222
CVM2

Terminate scanning operations.

ETM  Date 8-10-01

50-23

CTIF CVM1 222
CVM2

Perform Operation 100 - Console Securing.

ETM  Date 8-10-01

50-24

CTIF

If LO₂/LH₂ tanking started, **perform** Operation 110 - Summary
Tape.

ETM  Date 8-10-01

Not Performed: N/A

50-11

8/10/01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

NOTE

Following step may be not performed at CTIF discretion.

50-25 CTIF TBC 136
 TBC STM

If Post Drain Walkdown to occur at night, **request** PAD xenon lighting be maintained/activated for duration of walkdown.

Not Performed: 8-10-01

NOTE

Post drain walkdown typically commences approximately 1.5 hours after LH₂/LO₂ low level sensors read dry.

50-26

CTIF

If launch scrubbed after start of LO₂/LH₂ tanking, **perform** Operation 120 - Post-Drain Walkdown.

ETM N/A Date 8-10-01 ^{NA}

Not Performed: 8-10-01

50-27

CTIF

If launch occurred, **perform** Operation 130 - Post launch Walkdown.

ETM [Signature] Date 8-10-01

Not Performed: N/A

ET
01

8/10/01

*VOID - NA - EIE
8/10/01 50-12

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

50-28

CTIF

If launch occurred, **perform** Operation 140 - Film Review.

ETM

J. Seac Date 5/2/01

Not Performed: N/A

50-29

SSV Debris Assessment complete.

50-13

EF
01

5/2/01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 50-1 Observation Documentation Procedure

1. CTIF CVM1 222 Locate anomaly/concern on pertinent OTV(s)
CVM2
2. CTIF Punch-up pertinent OTV on trouble monitor.
Update trouble tape log in table below.
3. CTIF Start the trouble tape.

NOTE

Trouble tape shall be allowed to run until sufficient OTV documentation of observation/concern has been made. OK to change OTV's while trouble tape is running.

4. CTIF After observation/concern has been documented on the trouble tape, stop the trouble tape. Update trouble tape log below.

TROUBLE TAPE LOG

Trouble Tape No.	Start Time (GMT)	Stop Time (GMT)	OTV	Description
02	13:23	13:28	63,8	WATER DRIPPING FROM DAA
02	13:30	13:32	54	LOX F/L SCAN
02	13:58	13:59	061	1 st F/L Scan - 2003
02	14:25	14:34	009	LH2 F/L FROM 301
02	14:34	14:36	054	LOX F/L SCAN
02	15:44	15:45	054	LOX F/L SCAN
02	16:39	16:41	054	LOX F/L SCAN
02	17:30	17:33	054	LOX F/L SCAN
02	18:05	18:06	061	FROST BALLS ON VALVEYS
02	18:07	18:10	052	SPRINKLER 3 & 4 LOX F/L SCAN

OMI S6444 J01
APPROVED

TROUBLE TAPE LOG

[illegible]

5/10/21

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 50-2 Observation Worksheet

OBSERVATION DOCUMENTATION

Record following information for condition observed:

Observation No. 1

Observed By: W447 E TM

Date 8-10-01 Time 17:23 ^{7:23 from 15:00} GMT 13:23

Camera No. (or Walkdown) 63 + 8

Description:

Water dripping from orbiter access door.

Acceptance Rationale (or IPR/PR No.):

water is not hitting orbiter. Water is not being
produced by a leak.

CICE [Signature] Date 8/10/01
CTIF [Signature] Date 8-10-2001
Legend

ET
01

8/10/01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 50-2 Observation Worksheet

OBSERVATION DOCUMENTATION

Record following information for condition observed:

Observation No. 2

Observed By: USA ETM

Date 8/10/01 Time 9:30 GMT 13:30

Camera No. (or Walkdown) 61

Description:

3 frost spots in each of two valleys just
off of LOZ/347 spine - 2 side of "Y" marker

Acceptance Rationale (or IPR/PR No.):

Frost is not in debris zone of crater. - from
interior valleys is common on every tanking - from 10/2/01 8:10 AM
Situation is similar to photo 2.3.8 of N473 C5303,
however frost in this case is caused by thin scented foam.

CICE [Signature] Date 8/10/01
CTIF [Signature] Date 8/10/2001
Ken Legett

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 50-2 Observation Worksheet

OBSERVATION DOCUMENTATION

Record following information for condition observed:

Observation No. 3

Observed By: W. J. [illegible]

Date 8-10-01 Time 10:25 GMT 19:25

Camera No. (or Walkdown) 009

Description:

Front ball on LME F/L to LME tank interfere

Acceptance Rationale (or IPR/PR No.)

Front ball expected dissipated due
to compensate run off

CICE [Signature] Date 8/10/01

CTIF [Signature] Date 8/10/2001

ET
CI
8/10/01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 50-2 Observation Worksheet

OBSERVATION DOCUMENTATION

Record following information for condition observed:

Observation No. _____

Observed By: _____

Date _____ Time _____ GMT _____

Camera No. (or Walkdown) _____

Description:

Acceptance Rationale (or IPR/PR No.):

N/A

CICE _____ Date _____

CTIF _____ Date _____

1/3/01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 50-2 Observation Worksheet

OBSERVATION DOCUMENTATION

Record following information for condition observed:

Observation No. _____

Observed By: _____

Date _____ Time _____ GMT _____

Camera No. (or Walkdown) _____

Description:

Acceptance Rationale (or IPR/PR No. 11/1)

CICE _____ Date _____

CTIF _____ Date _____

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 50-2 Observation Worksheet

OBSERVATION DOCUMENTATION

Record following information for condition observed:

Observation No. _____

Observed By: _____

Date _____ Time _____ GMT _____

Camera No. (or Walkdown) _____

Description:

Acceptance Rationale (or IPR/PR No.):

N/A

CICE _____ Date _____

CTIF _____ Date _____

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 50-2 Observation Worksheet

OBSERVATION DOCUMENTATION

Record following information for condition observed:

Observation No. _____

Observed By: _____

Date _____ Time _____ GMT _____

Camera No. (or Walkdown) _____

Description:

Acceptance Rationale (or IPR/PR No.)

NA

CICE _____ Date _____

CTIF _____ Date _____

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 50-2 Observation Worksheet

OBSERVATION DOCUMENTATION

Record following information for condition observed:

Observation No. _____

Observed By: _____

Date _____ Time _____ GMT _____

Camera No. (or Walkdown) _____

Description:

Acceptance Rationale (or IPR/PR No.) N/A

CICE _____ Date _____

CTIF _____ Date _____

*** End of Table 50-2 Observation Worksheet ***

*** End of Operation 50 ***

8/31/01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

OPERATION 60 Group 1 Monitoring LO₂ Chill Down Thru T-0

Shop: SE
Cntrl Rm Console: FR2
OPR: ETM
Zone: NA
Hazard (Y/N): N
Duration (Hrs): 15.0

NOTE

Do not perform this operation if launch scrub declared before LO₂ Chill Down commences.

Operation Not Performed: W/A

NOTE

This operation monitors LO₂ Ogive and Barrel and associated components/ areas from start of Chill Down through T-0 via OTV cameras 013/113, 060/160, 061/161, 062/162, 063/163 and 064/164.

OTV cameras 013/113 and/or 062/162 will view -Y GO₂ Vent Hood Seal at all times. At no time will both cameras be positioned away from the -Y GO₂ Vent Hood Seal.

OTV cameras 068/168 and 069/169 view SW and NE GO₂ Vent Areas respectively. These are fixed FOV cameras and do not have pan, tilt, etc. capability.

Steps in this operation are contingent upon progression of launch countdown operations and may be not performed if countdown is terminated.

Noted requirements satisfied by completion of this operation.

OMRS S00FB0.005-1

OMRS S00L00.150-1

WC
150
USA
Dev 60
AC 01
P

WC
150
USA JUN 12 '01

8/10/01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

LO₂ Chill Down To L-2 Hour Mark

60-1 CVM1 JYVR 138

At start of vehicle LO₂ Chill Down, **start** recorders for cameras 004/104, 013/113, 060/160, 061/161, 062/162, 063/163, 064/164, 068/168, and 069/169.

ETM R Brewer Date 8/10/01

Support: COMM

60-2 Record LO₂ MPS Chill Down start date and time (GMT).

LO₂ MPS Chill Down Date 8/10/01 GMT Time 12:24 GMT

ETM R Brewer Date 8/10/01

60-3 CVM1 JTV1 223

From start of LO₂ Chill Down until start of LO₂ Fast Fill on OTV cameras 004/104, 013/113, 060/160, 061/161, 062/162, 063/163, 064/164, 068/168, and 069/169 **monitor/videotape** ET-TPS surfaces. No cryogenic liquid or excessive vapors allowed.

ETM R Brewer Date 8/10/01

Support: COMM

Not Performed: N/A

8/10/01

Table 60-1 CVM1 Camera Positions for Terminal Count

NOTE

This Table defines CVM1 camera positions for terminal countdown. Cameras should be positioned for ignition no later than pick-up of T-9 minutes count. "Spot" scanning after pick-up of the T-9 minute count is acceptable with CICE concurrence.

Cameras may be positioned for SSME ignition non-sequentially.

Camera positions may be altered real-time with CICE concurrence. Alterations should be determined prior to pick-up of T-9 minute count to allow sufficient time for operators to rehearse camera movements with ice console.

The GO₂ Vent Arm (GVA) retracts at T-2m30s.

CVM1 Camera Positions Are Defined As Follows:

004/104

GUCP centered in frame so that GUCP will stay in view throughout SRB "twang".

042/142

At approximately T-1 hour, view and monitor Orbiter access arm while Orbiter hatch is being closed.

At **T-7m30s**, watch Orbiter access arm retract, then view bipod strut in center of frame, LO₂ feedline fairing in top of frame, and Orbiter hatch in right of frame.

054/154

At **T-3m50s**, view Orbiter right hand body flap movement, then zoom out with Orbiter/ET umbilicals at approximate frame center, Orbiter trailing edge at frame bottom, and edge of +Y (RH) SRB just in view at frame right.

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 60-1 CVM1 Camera Positions for Terminal Count

013/113

At **T-2m30s**, watch lift of GO₂ vent arm for debris and nose cone/vent louvers for ice damage. Immediately following lift of GO₂ vent arm, center frame on GO₂ vent louver and then zoom-out so that entire ET movement is seen during SRB 'twang' at SSME ignition.

060/160

At approximately **T-2m30s**, after GO₂ vent arm retracts, go full zoom in for a close-up inspection of the GO₂ vent louver. After CICE concurrence, go full zoom out and position camera with SSV centered and ET nose cone at frame top.

062/162

At approximately **T-2m30s**, after GO₂ vent arm retracts, go full zoom in for a close-up inspection of the -Y GO₂ vent louver. After CICE concurrence, zoom out until ET nose spike is at top of frame with ET centered.

061/161

At approximately **T-4m00s**, verify camera lights are off. Then position camera to view astronaut closing visor at T-2 minutes 00 seconds.

068/168 and 069/169

Immediately after GO₂ vent hood lift, turn lights off to preclude distracting orbiter crew when the GVA rotates to its latchback position.

***** End of Table 60-1 Camera Positions for Terminal Count *****

***** End of Operation 60 *****

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Terminal Count Camera Positions

NOTE

This step performed for SSME ignition only and may be not performed if launch is scrubbed prior to pick-up of T-9 minute count. Cameras must be positioned for ignition no later than T-9 minutes. "Spot" scanning after pick-up of the T-9 minute count is acceptable with CICE concurrence.

Cameras may be positioned for SSME ignition in an arbitrary order.

Camera positions may be altered real-time with CICE concurrence. Alterations should be determined prior to pick-up of T-9 minute count to allow sufficient time for OTV operators to rehearse camera movements.

CVM1 camera positions for SSME ignition are defined in Table 60-1.

60-11 CVM1 JTV1 223

Ref Table 60-1, **position** cameras 004/104, 013/113, 042/142, 054/154, 060/160, 062/162 for terminal count.




ETM _____ Date 8-10-01

Support: COMM

Not Performed: N/A

60-12 ~~Completion of this operation satisfies noted OMRS requirements.~~



~~OMRSD S00FB0.005-1~~
~~OMRSD S00L00.150~~

110
WIA
KSN

ETM _____ Date _____

60-13 Operation - Group 1 Monitoring - LO₂ Chill Down Thru T-0 complete.

8/10/01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Final SSV Inspection Scan

NOTE

Final SSV Inspection Scan should begin not later than 1.5 hours prior to start of T-9 minute hold (approximately L-2 hours) to allow ample time to finish. Final SSV Inspection Scan shall include the ET, SRB's and the Orbiter.

Final scan may be altered or partially performed in the event that time constraints will not permit a complete SSV scan prior to start of T-9 minute hold.

During Final SSV Inspection Scan the camera lights on OTV cameras 061/161 and 062/162 shall be turned "Off" when view passes over the Orbiter cockpit to preclude "distracting" the Flight Crew.

60-10 CVM1 JTV1 223

Perform Final SSV Inspection Scan with OTV cameras 004/104, 013/113, 060/160, 061/161, 062/162, 063/163 and 064/164. Scan passes shall view entire SSV with cameras at approximate full zoom in during final scan.

ETM R. Brewer Date 08/10/01

Not Performed: N/A

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

60-7 Record LO₂ Topping date and time (GMT).

LO₂ Topping Date 8/10/01 GMT Time 15:04 GMT

ETM R Brewer Date 8/10/01

Not Performed: N/A

60-8 Record LO₂ Stable Replenish mode start date and time (GMT).

LO₂ Stable Replenish Date 8/10/01 GMT Time 15:12 GMT

ETM R Brewer Date 8/10/01

Not Performed: N/A

60-9 CVM1 JTV1 223

From time LO₂ Stable Replenish mode is established until time for final SSV scan (approximately L-2 hours), **monitor, scan and videotape** ET-TPS surfaces on OTV cameras 004/104, 013/113, 060/160, 061/161, 062/162, 063/163, 064/164, 068/168, and 069/169. No cryogenic liquid or excessive vapors allowed.

ETM R Brewer Date 8/10/01

Support: COMM

Not Performed: N/A

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

60-4 Record LO₂ Slow Fill start date and time (GMT).

LO₂ Slow Fill Date 08/10/01 GMT Time 12:58 GMT

ETM R Brown Date 08/10/01

Not Performed: N/A

60-5 Record LO₂ Fast Fill start date and time (GMT).

LO₂ Fast Fill Date 08/10/01 GMT Time 14:10 GMT 8-10-01
13:04

ETM R Brown Date 08/10/01

Not Performed: N/A

60-6 CVM1 JTV1 223

From start of LO₂ Fast Fill until LO₂ stable replenish mode is established.
monitor/videotape ET-TPS surfaces on OTV cameras 004/104, 013/113, 060/160, 061/161, 062/162, 063/163, 064/164, 068/168, and 069/169. **Scan** LO₂ Tank. **Alternate** cameras and **scan** from Intertank to LO₂ Barrel Splice to GO₂ Vent Hood. No cryogenic liquid or excessive vapors allowed.

ETM _____ Date 8/10/01

Support: COMM

Not Performed: N/A

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

OPERATION 70 Group 2 Monitoring - LH₂ Chill Down Thru T-0

Shop: SE
Cntrl Rm Console: FR2
OPR: ETM
Zone: NA
Hazard (Y/N): N
Duration (Hrs): 15.0

NOTE

Do not perform this operation if launch scrub declared before start of LH₂ Chill Down.

Operation Not Performed: N/A

NOTE

This operation monitors LH₂ Barrel and associated components/areas start of LH₂ Chill Down to pre-pressurization via OTV cameras 009/109, 033/133, 054/154, 055/155, 056/156, 065/165, 066/166 and 067/167.

Steps in this operation are contingent upon progression of launch countdown operations and may be not performed if countdown is terminated.

Noted requirements satisfied by completion of this operation.

OMRS S00FB0.005 1-

OMRS S00FB0.360 1

WC 150 USA
Dev 70
No 01
150 USA
Nov 12 '01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

LH₂ Chill Down To L-2 Hour Mark

70-1 CVM2 JYVR 138

At start of LH₂ Chill Down, start recorders for cameras 009/109, 033/133, 054/154, 055/155, 056/156, 065/165, 066/166 and 067/167.

ETM [Signature] Date 8/10/01

Support: COMM

70-2 Record LH₂ Chill Down start date and time (GMT).

LH₂ Chill Down Date 8/10/01 Time 2:16 GMT

ETM [Signature] Date 8/10/01

70-3 CVM2 JTV2 225

From start of propellant loading until start of LH₂ Fast Fill on OTV cameras 033/133, 054/154, 055/155, 056/156, 065/165, 066/166 and 067/167, monitor/videotape ET-TPS surfaces. No cryogenic liquid or excessive vapors allowed.

ETM [Signature] Date 8/10/01

Support: COMM

Not Performed: LA

8/10/01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

70-4 Record LH₂ Slow Fill start date and time (GMT).

LH₂ Slow Fill Date 8/10/01 Time 12:52 GMT

ETM Mark Wollan Date 8/10/01

Not Performed: NA

70-5 Record LH₂ Fast Fill start date and time (GMT).

LH₂ Fast Fill Date 8/10/01 Time 12:58 GMT

ETM Mark Wollan Date 8/10/01

Not Performed: NA

70-6 CVM2 JTV2 225

From start of LH₂ Fast Fill until stable replenish mode is established, scan LH₂ Tank. **Alternate** OTV cameras 033/133, 054/154, 055/155, 056/156, 065/165, 066/166 and 067/167 and **scan/videotape** from LH₂ Aft Dome to Intertank.

ETM Mark Wollan Date 8/10/01

Support: COMM

Not Performed: NA

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

70-7

Record start date and time (GMT) for LH₂ Topping.

LH₂ Topping Date 8/10/01 Time 17:10 GMT

ETM Mark W. Nelson Date 8/10/01

Not Performed: NA

70-8 Record LH₂ Stable Replenish mode start date and time (GMT).

LH₂ Stable Replenish Date 8/10/01 Time 17:10 GMT

ETM Mark W. Nelson Date 8/10/01

Not Performed: NA

70-9 CVM2 JTV2 225

During LH₂ Stable Replenish mode and until time for final scan (approximately L-1.5 hours), on OTV cameras 033/133, 054/154, 055/155, 056/156, 065/165, 066/166 and 067/167, **monitor/videotape** ET TPS surfaces including LO₂ Feed Line, LH₂ Feed Line, LH₂ Recirculation Line, LH₂ Aft Dome and manhole covers, LH₂/LO₂ Umbilicals, and TSM LH₂/LO₂ Umbilicals. No cryogenic liquid or excessive vapors allowed.

ETM Mark W. Nelson Date 8/10/01

Support: COMM

Not Performed: NA

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Final SSV Inspection Scan

NOTE

Final SSV Inspection Scan should begin not later than 1.5 hours prior to start of T-9 minute hold (approximately L-2 hours) to allow ample time to finish. Final SSV Inspection Scan shall include the ET, SRB's and the Orbiter.

Final SSV Inspection Scan may be altered or partially performed in the event that time constraints will not permit a complete SSV scan prior to start of T-9 minute hold.

70-10 CVM2 JTV2 225

Perform Final SSV Inspection Scan with OTV cameras 009/109, 033/133, 054/154, 055/155, 056/156, 065/165, 066/166 and 064/164. Scan passes shall view entire SSV with cameras at full zoom in during final scan.

ETM Tom Ford Date 8-10-01

Support: COMM

Not Performed: N/A

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

T-9 Minute Terminal Count

NOTE

Next step performed for terminal count only and may be not performed if launch is scrubbed prior to pick-up of T-9 minute terminal count. Cameras must be positioned for SSME ignition no later than T-9 minutes. 'Spot' scanning after pick-up of the T-9 minute terminal count is acceptable with CICE concurrence.

Cameras may be positioned for SSME ignition in an arbitrary order.

Camera positions may be altered real-time with CICE concurrence. Alterations should be determined prior to pick-up of T-9 minute count to allow sufficient time for OTV operators to rehearse camera movements.

CVM2 camera positions for terminal count are defined in Table 70-1.

70-11 CVM2 JTV2 225

Ref Table 70-1, **position** cameras 009/109, 033/133, 056/156, 065/165, 066/166, 061/161, 070/170, 071/171 and 067/167 for terminal count.

ETM Tom Ford Date 8/10/01

Support: COMM

Not Performed: N/A

70-12 ~~Completion of this operation satisfies noted OMRS requirements.~~

WC
150
USA
Dev 70
No 01
P
WC
150
USA

~~OMRSD S00FB0.005-1~~
~~OMRSD S00FB0.360-1~~

ETM _____ Date _____

70-13 Operation - Group 2 Monitoring - LH₂ Chill Down Thru T-0 complete.

8/10/01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 70-1 - CVM2 Camera Positions for Terminal Count

NOTE

This Table defines CVM2 camera positions for terminal countdown. Cameras should be positioned for ignition no later than pick-up of T-9 minutes count. "Spot" scanning after pick-up of the T-9 minute count is acceptable with CICE concurrence.

The Orbiter access arm (OAA) retracts at T-7M30S. Orbiter body flap movement occurs at T-3m50s.

Cameras may be positioned for SSME ignition non-sequentially

Camera positions may be altered real-time with CICE concurrence. Alterations should be determined prior to pick-up of T-9 minute count to allow sufficient time for operators to rehearse camera movements with ice console.

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Group 2 Camera Positions Are Defined As Follows:

033/133

Full zoom out. LO₂ feed line in frame center and MLP deck at bottom.

055/155

View ET aft dome with MLP deck just out of view at bottom, ET XT-2058 ring frame at frame top and both SRB's just in view at sides.

056/156

View ET aft dome with MLP deck just out of view at bottom. ET XT-2058 ring frame at frame top and both SRB's just in view at sides.

065/165

Full zoom out. SSV centered. MLP deck edge just in view at bottom.

066/166

ET centered. Intertank to LO₂ Barrel splice at frame top with the majority of Orbiter wing in view.

067/167

Center on GUCP for optimum view.

070/170 and 071/171

At T-9m00s. zoom in on space shuttle main engine with camera providing best view. Zoom out on SSME for wide angle view with other camera.

009/109

At approximately T-3m50s. position to view Orbiter body flap and elevons movement. Afterwards. center on LH₂ umbilical with -Y vertical strut at frame top.

061/161

At approximately T-1m30s. tilt-up to GO₂ Vent Footprint. Zoom in. Pause. If footprint is acceptable. zoom out and tilt down to view Orbiter nose/cockpit through liftoff.

*** End of Table 70-1 - CVM2 Camera Positions for Terminal Count ***

*** End of Operation 70 ***

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

OPERATION 80 Final Inspection

Shop: SE
Cntrl Rm Console: FR2
OPR: ETM
Zone: PAD A/B
Hazard (Y/N): Y
Duration (Hrs): 3.0

NOTE

Final Inspection may not need to be performed depending on LO₂/LH₂ tanking and launch countdown, as determined by CTC/TTL.

Final Inspection Team stay time guidelines for each level are given in Table 80-1. These guidelines are for reference only and may be deviated from at PICE discretion.

Operation Not Performed: N/A

01-15-2001
APPROVED

OMI S6444 J01
APPROVED




Figure 80-1: Deck (0) Level
(For Reference Only)





Figure 80-2: Deck (0) and 95 Ft Levels
(For Reference Only)

4-12-95



S6444-F 003

Figure 80-3: 135 and 195 Ft Levels
(For Reference Only)

8/10/01




Figure 80-4: 215 and 255 Ft Levels
(For Reference Only)

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

WARNING

Personnel working at heights greater than 4 feet and within 6 feet of an unguarded edge shall wear a **safety harness** with a **lanyard** secured to an approved tie off point, substantial structural member (no handrails) or a properly installed life line.

WARNING

Personnel performing final inspection shall be attired in **Nomex coveralls with gloves and hoods**. Personnel shall have available gloves, hoods, and **ELSA** at all times during walkdown.

Personnel using Sony DKC-ID1 camera shall verify lithium ion battery is securely locked in bayonet connector and the lithium button battery door is locked and taped in place. Personnel shall ensure the flash is not activated on the camera.

Personnel using Kodak DC-50/120 shall verify alkaline batteries are properly installed and the flash is not active on the camera.

Personnel using digital cameras (Sony DKC ID1, Kodak DC-50/120 shall not use these cameras in the presence of a hydrogen leak or an oxygen enriched atmosphere (readings greater than 23 percent O₂).

NOTE

Task Team Leader (TTL) for final inspection is PH-H. Additional personnel (listed below) may be added to the final inspection team with CTC, Launch Director, and Safety concurrence.

JSC Level II	(1)
PH-H	(2)
SFOC ETM	(1)

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

80-1 Assemble following final inspection team members:

TTL - PH-H (1)
PH-H (1)
SFOC ETM (2)
LMSSC LSS (1)
SFOC Safety (1)

80-2 Final inspection team **perform** walkdown of SSV and associated facilities as follows:

NOTE

Tables 80-2 and 80-3 are reference only items. Images are to be taken of targets of opportunity. Images must be taken with 35 mm and digital cameras. Digital images shall be inputted into SIMS.

1. Ref Tables 80-2 and 80-3, photograph SSV points of opportunity during final inspection using 35 mm. **Record** data.

Roll No. N/A

Negative No. N/A

Work order No. N/A

2. Reference Tables 80-2 and 80-3. **take** digital image of SSV points of opportunity using digital camera.

Description: Final Inspection Team

3. See Figures 80-1 through 80-4. **measure and record** (deg F) SSV external surface temperatures using IR gun(s)/scanners.

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

NOTE

The following substep references inspection areas. However, inspection shall not be limited to these areas. Inspection shall be of entire SSV and specific areas of concern as defined by the TTL, CTC, or Launch Director.

4. Visually inspect:

- Orbiter aft engine compartment external surfaces for condensation and ice formations.
- ET TPS surfaces which cannot be observed by the OTV system.
- Specific areas of concern as determined by the TTL, CTC, or Launch Director.

OMRSD S00U00.020-A-1

OMRSD S00U00.020-C-1

OMRSD S00U00.020-D-1

USA
M
110

80-3 Final Inspection complete. **Verify** no constraints to continue.

TTL (PH-H)

Date

9/10/01

SFOC-ETM

Date

8-10-01

80-4 Operation - Final Inspection complete.

ETM

ARE
02

Date

8-10-01

ET
01

8/10/01

80-8

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 80-1 Final Inspection Team Walkdown Stay Times

255 Ft Level - 5 Minutes

- LO₂ Ogive and Barrel acreage
- GO₂ Pressurization Line
- LO₂ Tank Cable Tray
- Visible LH SRB surfaces
- GO₂ Vent Ducts

215 Ft Level - 20 Minutes

- ET GH₂ 7 inch Vent Assembly
- ET acreage (between -Z and -Y axis)
- GO₂ vent area
- Orbiter tiles
- Visible SRB surfaces
- Inter tank-to-LO₂ Barrel splice

195 Ft Level - 10 Minutes

- LO₂ Feed Line
- ET/Orbiter Bipods (side and bottom view)
- -Y ET/SRB forward attachment (bottom view)
- -Y ET/SRB aft attachments (top view)
- Inter tank splice areas (LO₂ and LH₂)
- ET acreage (between -Y and +Z axis)
- Orbiter tiles
- Visible LH SRB surfaces

135 Ft Level - 10 Minutes

- LH₂ ET/Orbiter Umbilical
- -Y ET/SRB C/T
- -Y Vertical Strut
- LO₂ Feed Line
- ET acreage between -Y axis and +Z axis
- ET/Orbiter attachments (top view)
- Visible LH SRB surfaces
- Orbiter aft fuselage

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 80-1 Final Inspection Team Walkdown Stay Times

0 Level - 30 Minutes

- LH₂ Aft Dome
- ET acreage around +Z axis
- ET acreage around -Z axis
- LO₂ Feed Line
- LH₂ Feed Line
- ET/Orbiter attachments - Bottom view
- ET/Orbiter LH₂ and LO₂ Umbilicals
- T-0 LH₂ and LO₂ Umbilicals
- Space Shuttle Main Engines (SSME)
- Orbiter tiles
- ET/SRB aft attachments
- Visible SRB surfaces
- SRB ignition overpressure sound suppression water troughs

*** End of Table 80-1- Final Inspection Team Walkdown Stay Times ***

8/10/01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 80-2 Final Inspection Team - Telephotos

TELEPHOTOS - 255 FT LVL

<u>Photo</u>	<u>Camera Orientation</u>	<u>Notes</u>
GO ₂ Vent Ducts	Horizontal	
LO ₂ Acreage	Vertical	

TELEPHOTOS - 215 FT LVL

<u>Photo</u>	<u>Camera Orientation</u>	<u>Notes</u>
-Y Bipod Ramp	Horizontal	From RSS
LO ₂ P/L Ice Frost Ramps	Vertical	From RSS; Requires 3-4 shots
GO ₂ Seal/Hood	Horizontal	From haunch & RSS
GUCP	Vertical	

TELEPHOTOS - 195 FT LVL

<u>Photo</u>	<u>Camera Orientation</u>	<u>Notes</u>
-Y Bipod Ramp & Jack PAD C/O	Horizontal	

TELEPHOTOS - 135 FT LVL

<u>Photo</u>	<u>Camera Orientation</u>	<u>Notes</u>
LH ₂ UMB	Horizontal	
-Y Longeron	Vertical	If needed
Jack Pad Closeouts	Horizontal	
LH ₂ Acreage	Vertical	

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 80-2 Final Inspection Team - Telephotos

TELEPHOTOS - MLP

<u>Photo</u>	<u>Camera Orientation</u>	<u>Notes</u>
LH ₂ UMB	Horizontal	From West
LH ₂ UMB	Horizontal	From NW
EB-7	Horizontal	
EB-8	Horizontal	
LH ₂ Aft Dome	Horizontal	
Third Hard Point C/O	Vertical	
LH ₂ Barrel	Horizontal	From North
SSV Overall	Horizontal	From North
SSV Overall	Horizontal	From East
LO ₂ F/L Bracket & Bellows	Vertical	XT-1973
LO ₂ F/L Bracket	Vertical	XT-1871
LO ₂ F/L Bracket	Vertical	XT-1623
LO ₂ F/L Bracket	Vertical	ST-1377 & XT-1129
LO ₂ F/L Bracket & Bellows	Vertical	XT-1129 & XT-1106 from SE
LO ₂ P/L & C/T	Vertical	From SE

600 MM PHOTOS - 255 FT LVL

<u>Photo</u>	<u>Shutter Speed</u>	<u>Notes</u>
GO ₂ Vent Ducts	1/30	Contingency

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 80-2 Final Inspection Team - Telephotos

600 MM PHOTOS - 215 FT LVL

<u>Photo</u>	<u>Shutter Speed</u>	<u>Notes</u>
-Y GO ₂ Seal	1/30	
-Y Bipod Ramp	1/30	Contingency
Jack Pad C/O's	1/4	Difficult if windy
LO ₂ F/L	1/15	
-Y Vertical Strut (Crack)	1/30	

600 MM PHOTOS - 195 FT LVL

<u>Photo</u>	<u>Shutter Speed</u>	<u>Notes</u>
-Y Bipod Ramp	1/30	Contingency

600 MM PHOTOS - 135 FT LVL

<u>Photo</u>	<u>Shutter Speed</u>	<u>Notes</u>
LH ₂ UMB	1/30	
-Y Vertical Strut (Crack)	1/60	
LO ₂ F/L Bellows	1/15	Contingency

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 80-2 Final Inspection Team - Telephotos

600 MM PHOTOS - MLP

<u>Photo</u>	<u>Shutter Speed</u>	<u>Notes</u>
LH ₂ UMB	1/30	From West
LH ₂ UMB	1/30	From NW
LH ₂ UMB	1/30	From East
LH ₂ UMB Actuator C/O	1/15 or 1/30	From North standing next to water pipe
LO ₂ UMB	1/5	Lower Inboard
LO ₂ UMB	1/8	Inboard
LO ₂ F/L Bracket & Bellows	1/15	One photo to include XT-1978 & XT-1973
LO ₂ F/L Bracket	1/15	XT-1871
LO ₂ F/L Bracket	1/15	XT-1623
LO ₂ F/L Bracket	1/15	XT-1377
LO ₂ F/L Bracket	1/30	One photo to include XT-1129 & XT-1106
LO ₂ F/L Bracket	1/30	From SE corner; One photo to include XT- 1129 & XT-1106
Jack Pad C/O's	1/15	From SE corner
Ice Frost Ramps or Pal Ramps	1/15 or 1/30	Contingency
LH ₂ UMB Inboard	1/15	From East
+Y Longeron	1/15 or 1/30	Contingency
-Y Longeron	1/15	Contingency

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 80-2 Final Inspection Team - Telephotos

WIDE ANGLE PHOTOS - 255 FT LVL

<u>Photo</u>	<u>Camera Orientation</u>	<u>Lens</u>	<u>Notes</u>
LO ₂ Tank	Vertical	35-70 mm	
GO ₂ Vent Ducts	Horizontal	35-70 mm	

WIDE ANGLE PHOTOS - 215 FT LVL

<u>Photo</u>	<u>Camera Orientation</u>	<u>Lens</u>	<u>Notes</u>
Overall GH ₂ Vent Line	Horizontal	35-70 mm	
Orbiter Nose, ET -Y Side	Horizontal	35-70 mm	
Orbiter Nose, ET -Y, +Z Side	Horizontal	35-70 mm	From RSS
Forward Half of Vehicle	Vertical	28 mm	From RSS
Entire Orbiter	Vertical	28 mm	From RSS

WIDE ANGLE PHOTOS - 195 FT LVL

<u>Photo</u>	<u>Camera Orientation</u>	<u>Lens</u>	<u>Notes</u>
Aft Part of SSV, LH Wing	Vertical	35-70 mm	
Orbiter Fwd Section, Upper LH ₂ Tank	Vertical	35-70 mm	
Bipod, -Y, +Z Intertank Area	Horizontal	35-70 mm	

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 80-2 Final Inspection Team - Telephotos

WIDE ANGLE PHOTOS - 135 FT LVL

<u>Photo</u>	<u>Camera Orientation</u>	<u>Lens</u>	<u>Notes</u>
Orbiter Aft Section	Vertical	35-70 mm	
Lower LH ₂ Tank & LH SRB	Vertical	35-70 mm	

WIDE ANGLE PHOTOS - MLP

<u>Photo</u>	<u>Camera Orientation</u>	<u>Lens</u>	<u>Notes</u>
Overall Orbiter Left Side	Vertical	28 mm	
ET -Y, +Z Quadrant	Vertical	28 mm	
ET -Z Side	Vertical	28 mm	
ET +Y, +Z Quadrant	Vertical	28 mm	
Overall Orbiter Right Side	Vertical	28 mm	
ET Aft Dome	Horizontal	35-70 mm	
-Z Side of LO ₂ T-0; RCS Stinger	Horizontal	35-70 mm	
+Z Side of LO ₂ T-0; RCS Stinger OMS Nozzle	Horizontal	35-70 mm	
-Z Side of LH ₂ T-0; RCS Stinger	Horizontal	35-70 mm	
+Z Side of LH ₂ T-0; RCS Stinger OMS Nozzle	Horizontal	35-70 mm	
Overall SSME Cluster	Horizontal	50 mm	-Y Side
SSME No. 2	Horizontal	50 mm	
SSME No. 1, -Z Side	Horizontal	50 mm	
SSME No. 3	Horizontal	50 mm	

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 80-2 Final Inspection Team - Telephotos

Overall SSME Cluster	Horizontal	50 mm	+Y Side
LO ₂ UMB Area	Horizontal	35-70 mm	
LH ₂ UMB Area	Horizontal	35-70 mm	
ET/ORB UMB & ORB Lower Surface	Horizontal	28 mm	From under ET

*** End of Table 80-2 Final Inspection Team - Telephotos ***

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 80-3 Reduced Final Inspection Team Photos

WIDE ANGLE & TELEPHOTO PHOTOGRAPHY - 255 FT LVL

<u>Photo</u>	<u>Camera Orientation</u>	<u>Lens</u>	<u>Notes</u>
GO ₂ Vent Ducts	TELE	Horizontal	

WIDE ANGLE & TELEPHOTO PHOTOGRAPHY - 215 FT LVL

<u>Photo</u>	<u>Camera Orientation</u>	<u>Lens</u>	<u>Notes</u>
-Y Bipod Ramp	Horizontal	TELE	From RSS
LO ₂ P/L Ice/Frost Ramps	Vertical	TELE	From RSS; 2 photos required
GO ₂ Seal/Hood	Horizontal	TELE	From RSS
GUCP	Vertical	TELE	
Fwd Half of SSV	Vertical	28 mm	From RSS
Entire Orbiter	Vertical	28 mm	From RSS

WIDE ANGLE & TELEPHOTO PHOTOGRAPHY - 195 FT LVL

<u>Photo</u>	<u>Camera Orientation</u>	<u>Lens</u>	<u>Notes</u>
-Y Bipod Ramp & Jack Pad C/O's	Horizontal	TELE	

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 80-3 Reduced Final Inspection Team Photos

WIDE ANGLE & TELEPHOTO PHOTOGRAPHY - 135 FT LVL

<u>Photo</u>	<u>Camera Orientation</u>	<u>Lens</u>	<u>Notes</u>
LH ₂ UMB	Horizontal	TELE	
Orbiter Aft Section	Vertical	35-70 mm	

WIDE ANGLE & TELEPHOTO PHOTOGRAPHY - MLP DECK

<u>Photo</u>	<u>Camera Orientation</u>	<u>Lens</u>	<u>Notes</u>
LH ₂ UMB	Horizontal	TELE	From West
ET Aft Dome	Horizontal	TELE	
Aft Hard Point Closeout	Vertical	TELE	
LH ₂ Tank	Horizontal	TELE	From North
LO ₂ Tank	Horizontal	TELE	From North
LO ₂ Tank	Horizontal	TELE	From East
LO ₂ F/L Bracket Bellows	Horizontal	TELE	XT - 1978 & XT - 1973
LO ₂ F/L Bracket	Horizontal	TELE	XT - 1871
LO ₂ F/L Bracket	Horizontal	TELE	XT - 1623
LO ₂ F/L Brackets	Horizontal	TELE	XT - 1377 & XT - 1129
LO ₂ F/L Brackets & Bellows	Horizontal	TELE	XT - 1129 & XT - 1108; from SE
LO ₂ P/L & C/T	Horizontal	TELE	From SE
Overall Orbiter Left Side	Vertical	28 mm	
ET -Z Side	Vertical	28 mm	
Overall Orbiter Right Side	Vertical	28 mm	
Overall SSME Cluster -Y Side	Horizontal	28 mm	

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 80-3 Reduced Final Inspection Team Photos

Overall SSME Cluster +Y Side	Horizontal	28 mm	
ET/Orb UMB & Orbiter Lower Surface	Horizontal	28 mm	From under ET

*** End of Table 80-3 - Reduced Final Inspection Team Photos ***

*** End of Operation **80** ***

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

OPERATION 90 LO₂/LH₂ Drain Monitoring

Shop: SE
Cntl Rm Console: FR2
OPR: ETM
Zone: NA
Hazard (Y/N): N
Duration (Hrs): 4.0

NOTE

This operation is contingent upon progression of launch countdown and is performed after start of cryo (LO₂/LH₂) loading and subsequent launch scrub, FRF, or WCDDT.

Operation Not Performed: 

8-10-01

NOTE

This operation monitors the External Tank external surfaces during LO₂/LH₂ drain operations from time of detanking until 1.5 hours after LO₂/LH₂ low level sensors read dry via OTV 004/104, 009/109, 013/113, 033/133, 042/142, 054/154, 055/155, 056/156, 060/160, 061/161, 062/162, 063/163, 064/164, 065/165, 066/166, 067/167, 068/168, 069/169, 070/170, and 071/171.

Noted requirements satisfied by this operation: OMRS S00E00.021

90-1 Record start date/time (GMT) of LH₂ and LO₂ Tank Drain.

LH₂ Drain Start Date N/A Time N/A GMT

LO₂ Drain Start Date N/A Time N/A GMT

ETM N/A Date N/A

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

90-2 CVM1 JTV1 223

From start of LO₂ Tank Drain and LH₂ Tank Drain until respective LO₂/LH₂ low level sensors read dry, **monitor** ET external surfaces including LO₂ Feed Line, LH₂ Feed Line, LH₂ Recirculation Line, LH₂ Aft Dome and manhole covers, LH₂/LO₂ Umbilicals, TSM LH₂/LO₂ Umbilicals via OTV cameras. No cryogenic liquid or excessive vapors allowed.

ETM N/A Date N/A

Support: COMM

90-3 Record date/time (GMT) when LO₂/LH₂ low level sensors read dry.

LH₂ Sensors Dry Date N/A Time N/A GMT

LO₂ Sensors Dry Date N/A Time N/A GMT

ETM N/A Date N/A

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

90-4 CVM1 JTV1 223

Monitor ET external surfaces including LO₂ Feed Line, LH₂ Feed Line, LH₂ Recirculation Line, LH₂ Aft Dome and manhole covers, LH₂/LO₂ Umbilicals, TSM LH₂/LO₂ Umbilicals via OTV cameras for 1.5 hours after LO₂/LH₂ low level sensors have read dry. No cryogenic liquid or excessive vapors allowed. Record date/time (GMT) when monitoring complete.

LH₂ Complete Date N/A Time N/A GMT

LO₂ Complete Date N/A Time N/A GMT

ETM N/A Date N/A

Support: COMM

90-5 Completion of this operation satisfies noted requirements.

USA
VM
067 OMRSD S00E00.021

90-6 Operation - LO₂/LH₂ Drain Monitoring complete.

*** End of Operation 90 ***

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

OPERATION 100 Console Securing

Shop: SE
Cntrl Rm Console: FR2
OPR: ETM
Zone: NA
Hazard (Y/N): N
Duration (Hrs): 0.5

100-1

CTIF	TBC	136
TBC	CTC	232

OTV support for ET thermal protection system evaluation no longer required.

100-2

CTIF	JYVR	138
------	------	-----

Perform the following:

1. Turn off video recorders.
2. Remove tape cartridges.
3. OTV support no longer required.

Support: COMM

100-3

CTIF	CVM1	222
	CVM2	

Secure consoles by setting all monitors to "Off" position.
Report completion.

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

NOTE

Perform next step only after a successful launch.

100-4

CTIF

Remove photo processing laptop computer from Firing Room.

Not Performed: N/A

100-5

CTIF	TBC	136
TBC	CTC	232

Firing Room 2, ice frost monitoring area securing complete.

100-6

Operation 100 - Console Securing complete.

ETM P. Seane Date 8/14/01

*** End of Operation 100 ***

8/14/01

100-2

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

OPERATION 110 Summary Tape

Shop: SE
Cntrl Rm Console: FR2
OPR: ETM
Zone: NA
Hazard (Y/N): N
Duration (Hrs): 18.0

NOTE

Observations/concerns observed during count are typically recorded on the summary tape real-time (trouble tape).

110-1 CICE

After launch or launch scrub, prepare a summary tape to include observations/concerns noted during count.

110-2 Operation Summary Tape complete.

ETM R. Seale Date 8/10/01

*** End of Operation 110 ***

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

OPERATION 120 Post Drain Walkdown

Shop: SE
Cntrl Rm Console: NA
OPR: ETM
Zone: PAD A/B
Hazard (Y/N): Y
Duration (Hrs): 2.0

NOTE

Post drain walkdown performed only after start of cryo (LH₂/LO₂) loading and subsequent launch scrub.

Operation Not Performed: 

8-10-01

WARNING

Personnel working at heights greater than 4 feet and within 6 feet of an unguarded edge shall wear a **safety harness** with a **lanyard** secured to an approved tie off point, substantial structural member (no handrails) or a properly installed life line.

Personnel shall wear **hardhats** and **flame retardant coveralls** while performing post drain walkdown.

NOTE

Post drain walkdown typically commences approximately 1.5 hours after LH₂/LO₂ low level sensors read dry.

Post drain walkdown performed in support of a 24 hour scrub turnaround is typically coincident with the L-20 hour pre-launch walkdown for the ensuing launch attempt.

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

NOTE

NASA ET Mechanical Engineer (PH-H) or designee shall function as team leader. Following personnel are walkdown optional participants:

NASA Engr	(4)
SFOC Engr	(2)
LMSSC-LSS	(1)
Boeing LSS	(1)
SFOC Safety	(1)

- 120-1** NASA Lead ET Mechanical Systems Engineer (PH-H) verify essential personnel on station, properly attired, and ready to proceed with post drain walkdown.

Essential Personnel

NASA Engineering (PH-H)	1
SFOC Engineering (ETM)	1

NOTE

"Hands-on Investigation" is applicable only to those areas which are not understood or fully defined and which cannot be adequately evaluated otherwise.

- 120-2** Perform post drain walkdown as follows:

- 1. Visually inspect** ET TPS exterior surfaces after detanking and warm-up (approximately T + 4 hours after drain is initiated) from the MLP, FSS, and RSS as access permits.
- 2. Perform** hands-on investigation of all areas suspected of violating Doc: NSTS 08303 (LI) NSTS PROGRAM ICE/DEBRIS INSPECTION CRITERIA (LI)

USA
VM
067

OMRSD S00E00.031

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

- 120-3 Walkdown complete. All discrepancies identified. No constraints to continue.

PH-H N/A Date N/A

ETM N/A Date N/A

- 120-4 Operation Post Drain Walkdown complete.

*** End of Operation 120 ***

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

OPERATION 130 Post Launch Walkdown

Shop: SE
Cntrl Rm Console: NA
OPR: ETM
Zone: PAD A/B
Hazard (Y/N): Y
Duration (Hrs): 3.0

NOTE

Do not perform this operation after launch scrub.

Operation Not Performed: N/A

WARNING

Personnel working at heights greater than 4 feet and within 6 feet of an unguarded edge shall wear a **safety harness** with a **lanyard** secured to an approved tie off point, substantial structural member (no handrails) or a properly installed life line.

Personnel participating in walkdown shall wear **hardhats** and **flame retardant coveralls**.

NOTE

NASA ET Mechanical Engineer (PH-H) or designee shall function as team leader. Following personnel are walkdown optional participants:

NASA Engr	(3)
SFOC Engr	(2)
LMSSC-LSS	(1)
Boeing LSS	(2)
SRB ELE	(1)
Thiokol-LSS	(1)
SFOC Safety	(1)

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

- 130-1 NASA (PH-H) verify following personnel on station, properly attired, and ready to proceed with post launch walkdown.

WC
150
USA
Dev 130
01
P 8/10/01
SEE DEV

Essential Personnel		
NASA	PH-H	1
SFOC	ETM	1

- 130-2 Perform Post Launch Walkdown as follows:

1. Ref Table 130-1, **visually inspect** post launch pad/area to identify any lost flight or ground systems hardware and debris sources.
2. Ref Table 130-2, **document/SIMS photograph** launch PAD area configuration.

Description: Post Launch Walkdown

OMRSD S00U00.010-1

UO
IA
USO

- 130-3 Walkdown complete. Debris sources and lost flight hardware identified. No constraints to continue.

PH-H [Signature] Date 8/10/01
ETM [Signature] Date 8/10/01

- 130-4 Operation - Post Launch Walkdown complete.

ET
01

8/10/01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 130-1 Post Launch Walkdown Inspection Areas

Record mission info, PAD, date, and time:

STS _____

PAD _____

Date _____

Time _____

SEE "STS 105
POST LAUNCH PAD
DEBRIS INSPECTION
REPORT" INSERT
AT STEP 150-1.

SRB Hold-down posts (HDP)

Inspect for damage, stud hang-up Epon shim material, ordnance fragments, doghouse
blast covers, erosion, missing hardware, debris. Record Results:

R. Sca ETM
8/14/01

N A

MLP Deck

SRB aft skirt purge lines
SRB T-0 umbilicals
Tail service masts (TSM's)
MLP deck

195 Ft Level

Orbiter access arm (OAA)

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 130-1 Post Launch Walkdown Inspection Areas

215 Ft Level - GH2 Vent Line/GUCP

Latch position
Loose cables
Damage from SRB plume
Damage to the QD

255 Ft Level - GO₂ Vent Arm, Ducts, Hood

Seals
Hood windows, doors, latches

Fixed Service Structure (FSS)

Cable tray covers
Signs
Hydraulic leaks
Slidewire baskets

PAD Apron/Acreage

Vehicle hardware and/or flight TPS materials
Facility debris

Table K-1 PAD Apron/Acreage Items

<u>Description</u>	<u>Location</u>

*** End of Table 130-1 - Post Launch Walkdown Inspection Areas ***

8/14/01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

Table 130-2 Post Launch Photos (MLP, FSS, PAD, Apron, Pad Acreage)

MLP 0-level

- 1 Ea HDP No. 1, 2, 5 & 6 (HDP shoe and Epon shim)
- 1 Ea HDP No. 3, 4, 7 & 8 (blast cover down to HDP base)
- 1 Ea SRB T-O umbilical
- 1 Ea overall view SRB exhaust cutouts\

Any unusual or debris-related damage to the facility; sound suppression water pipes, TSM's cracks in MLP deck, witness panels, handrails, etc.

Any flight hardware debris (tiles, SRB ordnance fragments)
Any facility debris (nuts, bolts, cable tray covers, etc.)

FSS

Close-ups of GUCP and latching mechanism
Overall views of GO₂ vent hood/ducts, if damaged
Any flight hardware or facility debris
Any unusual or debris-related damage to the facility

PAD Apron/PAD Acreage

Any flight hardware or unusual facility debris objects

Any unusual or debris-related damage to the PAD (such as missing brick in the flame trench), perimeter fence, etc.

*** End of Table 130-2 - Post Launch Photos (MLP, FSS, PAD, Apron, Pad Acreage) ***

*** End of Operation 130 ***

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

OPERATION 140 Film Review

Shop: SE
Cntrl Rm Console: NA
OPR: ETM
Zone: NA
Hazard (Y/N): N
Duration (Hrs): 15.0

NOTE

This operation may be not performed after launch scrub.

WC
150
USA
01
8/10/01
SEE DEV

Operation 140 Not Performed: N/A

140-1 Review engineering films for FOD issues, launch anomalies, or other discrepancies.

140-2 Operation - Film Review complete.

ETM K. Stone Date 8/20/01

*** End of Operation 140 ***

WC
013
USA
SEP 4 01

ET
8/20/01

WC
150
USA
JUN 8 01
Dev 140
02 P
8/14/01
SEE DEV

WC
150
USA
SEP 4 01
ENTERED
11/14/01

VOID
FILE
ET
01
2 pl
J. Sene
8/14/01

8/14/01

01-15-2001
APPROVED

OMI S6444 J01
APPROVED

OPERATION 150 Final Report

Shop: SE
Ctrl Rm Console: NA
OPR: ETM
Zone: NA
Hazard (Y/N): N
Duration (Hrs): 0.5

NOTE

This operation may be not performed after launch scrub.

Operation 150 Not Performed: N/A

- 150-1 Assemble final report by attaching following reports to this OMI.
Reference each to this step.

Post Launch PAD Assessment
SRB Assessment
Launch Film Review
Launch Day Video Review
Orbiter Landing Assessment
ET Separation Review

- 150-2 Final report assembly complete.

WC 150
USA
Dev. 150
No. 01 P

WC 150
USA
JUN 12 '01

~~OMRSD 800600.011-1~~

ETM Seena Date 5/2/01

- 150-3 Operation - Final Report complete.

*** End of Operation 150 ***

8/3/01

150-1
140-1

see new isola P

ET
01

5/2/01

STEP 150-1 \$6444 24-01-03

STS-105 POST LAUNCH PAD DEBRIS INSPECTION REPORT

KSC Debris Team

10 August 2001

The post launch inspection of the MLP-3, Pad A FSS and RSS was conducted on 10 August 2001 from Launch - 2 to 3.5 hours(1900 to 2030 EST).

No flight hardware was found.

Orbiter liftoff lateral acceleration data to predict stud hang-ups received from Boeing-Huntington Beach indicated that no SRB holddown stud hang-up had occurred, the reported value was 0.138. Evaluation of the MLP 0-level was performed and the south holddown studs were visually assessed as having no indication of hang-up. Erosion was typical for the north posts with some evidence of missing RTV at the HDP haunch interface. North holddown post blast covers and T-0 umbilical exhibited minimal exhaust plume damage. Both SRB aft skirt GN2 purge lines were intact, protective tape layering was partially eroded, the metal braid was visible only on the LH purge line.

The LO2 and LH2 Tail Service Masts (TSM) appeared undamaged and the LO2 bonnet was observed to have closed properly. The MLP deck was in generally good shape. A section of handrail on west side of the MLP deck was bent and had loose bolts. OTV-054 camera located on the east side of the MLP received extensive launch damage but no missing hardware was noticed. All MLP deck communication connector caps were found intact and secured.

The GH2 vent line latched in the eighth of eight teeth of the latching mechanism. The GUCP 7-inch QD sealing surface exhibited no damage. The deceleration cable was in nominal configuration, while the vent line blanket was sooted and in generally good condition.

The OAA appeared to be intact with no evidence of plume impingement.

All slidewire baskets were secured with no evidence of damage.

The GOX vent arm, hood, ducts and structure appeared to be in good shape with no indications of plume damage.

Debris findings included:

- A piece of twisted sheet metal 10 feet long by 18 inches wide was found near the box car area.
- An A/C duct clamp was found on deck grating at FSS 175 foot levels.

Overall, damage to the pad appeared to be minimal. Minimal debris was noted on pad apron and FSS.

Jorge Rivera NASA-KSC

8/10/01

STEP 15c - 1

\$6444 0004/07/01

STS-105 LAUNCH DAY VIDEO REVIEW

KSC Photo/Video Analysis Team

10 August 2001

Significant Anomalies - None

Minor Anomalies - None

Funnies - None

Observations

1. Free burning hydrogen was visible near the vertical stabilizer (OTV 070).
2. Numerous pieces of ice from the ET/ORB umbilical shook loose and contacted umbilical sill tiles, but no damage was detected (OTV 009, 063, 054, 061).
3. LH2 and LO2 T-0 umbilical disconnect was normal (OTV 049, 050).
4. Debris particle (probably ice from forward LO2 feedline bellows) was seen falling outboard of ET vertical strut near the ET/ORB interface shortly after SRB ignition. No contact with vehicle observed (OTV 009).
5. Two pieces of ice from forward LO2 feedline bellows observed falling between ET and Orbiter. One piece appears to contact orbiter lower surface (OTV 061).
6. Frost was visible around -Y and +Y ET GOX vent louver (OTV 060, 061).
7. Pieces of aft skirt instafoam fell out of the SRB plume during flight (TV-4, TV-13).
8. Localized flow condensation visible during ascent.
9. Tile surface coating material appeared to be missing from aft side of RH RCS stinger (OTV 051).

Notes

A total of 19 videos were made available for review. Review of long range tracking films is scheduled to begin Saturday, August 11, 2001.

Armando Oliu, NASA - KSC
Thomas Wilson, Boeing-KSC

STEP 150-1 2011 04103/STS 105

STS-105 POST LAUNCH FILM REVIEW

KSC Photo/Video Analysis Team

11 August 2001

Significant Anomalies - None

Minor Anomalies - None

Funnies - None

Observations

1. SRB separation appeared normal. (E-207, E-212,)
2. SSME Mach diamond formation sequence was 3-2-1. (E-76, -77)
3. Small amount of free-burning GH2 blown in a south-westerly direction by wind. (E-76, E-52)
4. Particles of SRB aft-skirt instafoam fell along side the SRB plume. (E-207, E-212)
5. Body flap and elevon movement during ascent were typical. (E-220, E-212)
6. A piece SRB water trough baggie observed moving upward and then aspirated by plume near RH SRB aft skirt between HDP #2 and #4.
7. Facility debris observed passing through field of view outboard of LH wing tip near FSS. (E-36)
8. Ice particles fell from ET/ORB umbilicals after lift-off. No impact to orbiter lower surface was noted. (E-31, E-36, E-52, E-63)
9. Charring on the ET aft dome was less than typical. (E-207)
10. Umbilical purge barrier baggie material fell during roll maneuver. (E-52, E-207)
11. Forward RCS paper covers were observed falling aft during early ascent.
12. Localized flow condensation observed at various points on the vehicle.
13. Numerous pieces of facility debris entered field of view well after vehicle cleared tower. (E-36, E-40).

Notes

Review of launch pad high-speed films will continue on Monday, August 13, 2001.

Armando Oliu, NASA - KSC
Robert Speece, NASA - KSC
Thomas Wilson, Boeing - KSC

g/f/

STEP 150-1 50414 01/03/5-1-05

STS-105 SRB POST FLIGHT/RETRIEVAL ASSESSMENT

KSC Debris Team

13 August 2001

The BI-109 Solid Rocket Boosters were inspected for debris damage and debris sources at CCAFS Hangar AF on 13 August 2001. Generally, both boosters were in excellent condition.

ANOMALIES - None

FUNNIES

The RH SRB top/left position forward BSM cover was missing. Preliminary examination of the fracture plane revealed no sooting effects, this is indicative of water impact damage.

OBSERVATIONS

1. The TPS on both frustums exhibited no debonds/unbonds. There was minor localized blistering of the Hypalon paint.
2. All seven remaining BSM aero heat shield covers had fully opened and locked. but one RH and two LH cover attach rings had been bent at the hinge by parachute riser entanglement.
3. The forward skirts exhibited no debonds or missing TPS. RSS antennae covers/phenolic base plates were intact, though one layer of the LH SRB +Z antenna phenolic base plate had delamination at the -Y edge.
4. The Field Joint Protection System (FJPS) and the System Tunnel Covers closeouts were generally in good condition with no unbonds observed.
5. Separation of the aft ET/SRB struts appeared normal.
6. Aft skirt external surface TPS was in good condition. Typical blistering of Hypalon paint had occurred on the BTA insulation close-outs and GEI cork runs.
7. The holddown post Debris Containment Systems (DCS) appeared to have functioned normally except on HDP No. 2 which was fully obstructed by the frangible nut halves. This condition most likely happened at water impact.
8. No indication of stud hang up was observed.

Armando Oliu, NASA-KSC
Robert Specce, NASA - KSC

STEP 15c-1

\$6444 CON 3/5-8/05

STS-105 POST LAUNCH FILM REVIEW

KSC Photo/Video Analysis Team

13 August 2001

SIGNIFICANT ANOMALIES - None

MINOR ANOMALIES - None

FUNNIES - None

OBSERVATIONS

1. No stud hang up, or ordnance fragments, were observed on any of the SRB hold-down posts.
2. Deluge water pipe leaking adjacent to HDP 3, water dripping on MLP deck. (E-7, E-10)
3. No OMS pod flexing observed. (E-17, E-18)
4. Piece of debris noted between HDP 2 and shoe. (E-8)
5. Free-burning GH2 blown toward southwest.
6. Several ice particles fell from ET/ORB umbilicals during SSME ignition.
7. Vapors on ET aft dome and SRB stiffener rings were observed after T-0.
8. Ice particles fell from LH2 / LO2 TSM T-0 disconnects.
9. Tile surface coating material was lost from aft face of RH OMS RCS stinger. This is a common occurrence due to SSME ignition acoustics. (E-19)
10. SRB throat plug material ejected from exhaust hole. No contact with vehicle.
11. Debris (probable SRB throat plug material RTV) ejected from adjacent to HDP 4, no vehicle contact noted. (E-7, E-15)
12. Dirty water visible dripping off of LH SRB nozzle. (E-9, E-10, E-13, E-15)

NOTES

All delivered launch films have been reviewed at this time.

Armando Oliu, NASA - KSC

Robert Speece, NASA - KSC

STEP 150-1 SC444 J00-KTS105

STS-105 POST LAUNCH FILM REVIEW

KSC Photo/Video Analysis Team

14 August 2001

SIGNIFICANT ANOMALIES - None

MINOR ANOMALIES - None

FUNNIES

Further analysis of Film Item E-18 shows a cylindrical shaped debris coming into view at GMT 21:10:15.643. As the item falls and tumbles it maintains a cylindrical shape. The debris is possibly a 3-inch long by 0.75-inch diameter facility bolt from the LH2 TSM.

An additional walk-down of the Pad was performed today and no hardware was found.

Launch Accessory personnel will be shown the film and inspections of the TSM will be performed to determine a source.

Armando Oliu, NASA - KSC

Jorge Rivera, NASA - KSC

STEP 150 - 1 \$6444 00-7/28/00

STS-105 ORBITER POST LANDING INSPECTION

PRELIMINARY DEBRIS ASSESSMENT

22 August 2001

A runway walkdown and preliminary post landing inspection of OV-103 Discovery was conducted at the Kennedy Space Center on SLF runway 15.

The Orbiter lower surface sustained 106 total hits, of which 15 had a major dimension of 1-inch or larger, both numbers are well within family. The majority of the hits (57 total with 11 greater than 1-inch) were located in the area from the nose landing gear to the main landing gear wheel wells on both left and right chines. The pattern and size ratio of these hits is indicative of damage from ET foam loss. Approximately 31 of the total lower surface hits were around the LH2 umbilical area. Most of these damage sites around the ET/ORB umbilical were most likely caused by pieces of the umbilical purge barrier flailing in the airstream and contacting tiles before pulling loose and falling aft.

The largest lower surface tile damage site, located on the LH chine area, measured 5-inches long by 4-inches wide by 0.0625-inches deep. The cause of this damage has not been determined yet.

The landing gear tires were reported to be in good condition.

ET/Orbiter separation devices EO-1, EO-2, and EO-3 functioned normally. No ordnance fragments were found on the runway beneath the umbilicals. The EO-2 and EO-3 fitting retainer springs appeared to be in nominal configuration, though one of the "salad bowl" clips was missing from EO-3. The EO-2/3 pyro debris shutters were fully closed. No debris was found beneath the umbilicals.

Typical amount of tile damage occurred on the base heat shield. All SSME Dome Heat Shield closeout blankets were in good condition.

Three vertical tail leading edge tile damage sites were observed, with two appearing to have a major dimension greater than one inch. There was one tile damage site on the leading edge of the RH OMS Pod.

There were a total of 31 hits, with 7 having one dimension greater than 1-inch, on the window perimeter tiles. Hazing and streaking of forward-facing Orbiter windows appears to be normal. A more detailed inspection will be performed in the OPF.

The post-landing walkdown of Runway 15 was performed immediately after landing. All components of the drag chute were recovered and appeared to have functioned normally. Several FOD items were found on the runway. The debris items found were: a 13-inch long, 10-gauge, metallic wire; a 1-inch long by 0.625-inches wide by 0.250 inches thick metal fragment, and numerous pieces of SLF concrete. All of which were found within

STEP 150-1

SL-144 01/01/01

10 feet of the center-line. Additionally, there were also numerous pieces of asphalt found on the approach threshold of runway 15.


In summary, the Orbiter TPS sustained a total of 137 hits, of which 24 had a major dimension of 1-inch or larger. This total does not include the numerous hits on the base heat shield attributed to SSME vibration/acoustics and exhaust plume recirculation.

The Orbiter post landing assessment will continue in OPF Bay 2 on Thursday 08/23/01.

Armando Oliu, NASA - KSC
Robert Speece, NASA - KSC
Mike Payne, NASA - KSC
Tony Crisafulli, Boeing-KSC

STEF 150-1
 STS - 105
 DEBRIS DAMAGE LOCATIONS


TOTAL HITS = 137
 HITS > 1 INCH = 24
 ALL DIMENSIONS
 IN INCHES



STP 15-1 56444 0010757108

STS - 105

DEBRIS DAMAGE LOCATIONS



STEP 15a-1

86947 00107/572005

STS - 105


DEBRIS DAMAGE LOCATIONS

RHS

TOTAL HITS = 0

HITS > 1 INCH = 0

ALL DIMENSIONS
IN INCHES




LHS

TOTAL HITS = 0

HITS > 1 INCH = 0

ALL DIMENSIONS
IN INCHES



ETEP 15-1

\$1444 00000000

STS-105 ORBITER POST LANDING INSPECTION

DEBRIS ASSESSMENT

22 August 2001

After the 2:23 p.m. local/eastern time landing on 22 August 2001, a post landing inspection of OV-103 Discovery was conducted at the Kennedy Space Center on SLF runway 15 and in Orbiter Processing Facility bay 2. This inspection was performed to identify debris impact damage and, if possible, debris sources.

The Orbiter TPS sustained a total of 144 hits of which 25 had a major dimension of 1-inch or larger. This total does not include the numerous hits on the base heat shields attributed to SSME vibration/acoustics and exhaust plume recirculation.

The following table lists the STS-105 Orbiter damage hits by area:

Area	Hits > 1-inch	Total Hits
Lower Surface	15	108
Upper Surface	2	3
Window Area	8	32
Right Side	0	0
Left Side	0	0
Right OMS Pod	0	1
Left OMS Pod	0	0
Totals	25	144

The Orbiter lower surface sustained 108 total hits, of which 15 had a major dimension of 1-inch or larger, both numbers are well within family. The majority of the hits (57 total with 11 greater than 1-inch) were located in the area from the nose landing gear to the main landing gear wheel wells on both left and right chines. The pattern and size ratio of these hits is indicative of damage from ET foam loss. This is the highest number of hits in this area since the implementation of ET intertank foam venting. Analysis of ET separation film will further aid in the determination of debris sources.

Approximately 31 of the total lower surface hits were around the LH2 umbilical area. Most of these damage sites around the ET/ORB umbilical were most likely caused by pieces of the umbilical purge barrier flailing in the airstream and contacting tiles before pulling loose and falling aft.

The largest lower surface tile damage site, located on the LH chine area, measured 5-inches long by 4-inches wide by 0.0625-inches deep. The cause of this damage has not been determined yet.

STEP 15.1

56444 0005/17/RS

The landing gear tires were reported to be in good condition.

ET/Orbiter separation devices EO-1, EO-2, and EO-3 functioned normally. No ordnance fragments were found on the runway beneath the umbilicals. The EO-2 and EO-3 fitting retainer springs appeared to be in nominal configuration, though one of the "salad bowl" clips was missing from EO-3. This condition was present prior to Orbiter/ET mate and was accepted per MR approval for unrestricted use back in 1999 via PR STR-5-14-3015. The EO-2/3 pyro debris shutters were fully closed. No debris was found beneath the umbilicals.

Typical amount of tile damage occurred on the base heat shield. All SSME Dome Heat Shield closeout blankets were in good condition.

Three vertical tail leading edge tile damage sites were observed, with two having a major dimension greater than one inch. There was one tile damage site on the leading edge of the RH OMS Pod.

There were a total of 32 hits, with 8 having one dimension greater than 1-inch, on the window perimeter tiles. Hazing and streaking of forward-facing Orbiter windows appears to be normal.

The post-landing walkdown of Runway 15 was performed immediately after landing. All components of the drag chute were recovered and appeared to have functioned normally. Several FOD items were found on the runway. The debris items found were: a 13-inch long, 10-gauge, metallic wire; a 1-inch long by 0.625-inches wide by 0.250 inches thick metal fragment, and numerous pieces of SLF concrete. All of which were found within 10 feet of the center-line. Additionally, there were also numerous pieces of asphalt found on the approach threshold of runway 15.

In summary, the total number of Orbiter TPS debris hits and the number of hits 1-inch or larger were within established family, however the number of hits between the main landing gear well and nose landing gear well is higher than normal. The potential identification of debris damage sources for mission STS-105 will be based on the laboratory analysis of Orbiter post landing microchemical samples, inspection of the recovered SRB components, film analysis, and aerodynamic debris particle trajectory analysis. The results of these analyses will be documented in the STS-105 Debris/Ice/TPS Assessment and Integrated Photographic Analysis report.

Armando Oliu
NASA - KSC

STEP 150-1

56444 0003/STB 105


STS - 105 DEBRIS DAMAGE LOCATIONS

Lower Surface Hits

Hits = 108

Hits > 1 inch = 15

All dimensions in inches



STEP 15-1

\$6444 0403/ST-105


STS - 105 DEBRIS DAMAGE LOCATIONS

Upper Surface Hits

Hits = 36

Hits > 1 inch = 10


All dimensions in inches




STEP 150-1 \$6444 CON STS 105

STS - 105 DEBRIS DAMAGE LOCATIONS

RHS
TOTAL HITS = 0
HITS > 1 INCH = 0
ALL DIMENSIONS
IN INCHES



LHS
TOTAL HITS = 0
HITS > 1 INCH = 0
ALL DIMENSIONS
IN INCHES



STEP 150-1 \$6444 00103/00105

STS-105 ON-ORBIT FILM SUMMARY

KSC Photo/Video Analysis Team

30 August 2001

The last film/video data, 35mm still images from the LO2 ET/ORB umbilical camera, 16mm motion picture with 5mm lens and Crew Hand-Held Still Images and video, of the External Tank after separation from the Orbiter were received and reviewed at KSC on 29 August 2001.

SIGNIFICANT ANOMALIES

None

MINOR ANOMALIES

None

FUNNIES

None

OBSERVATIONS:

1. SRB separation from the External Tank appeared nominal.
2. ET separation from the Orbiter was normal. There was no protrusion of the EO-2 and EO-3 separation bolt.
3. No damage was detected on the LO2 ET/ORB umbilical disconnect, sealing surfaces, or closeout TPS. Typical ablation and divoting was noted on the vertical portion of the umbilical cable tray.
4. There was an 8-inch diameter divot, with foam still partially attached, on the +Y thrust strut near the forward flange.
5. Divot observed on the LH2 tank near the base of the LO2 feedline support bracket closeout at station Xt-1377.
6. Missing foam (2-inches by 6-inches) observed on the LH2 tank acreage near the Xt-1270 location. Remainder of LH2 tank acreage appeared nominal.
7. Small divots observed on the intertank-to-LH2 tank flange between the bipods.
8. Evaluation of the thrust panel TPS was difficult due to lighting condition and image resolution.

ETP KSC-1 56444 CMC STS 105

9. No anomalies were detected in the LO2 tank acreage. The BSM burn scars were typical.
10. The ablation/erosion of LO2 feedline flange closeouts was typical.
11. Two small divots observed on the feedline at approximately station Xt-1270.

35mm umbilical film had no coverage LO2 ogive section. Evaluation of this area was difficult with 16mm film and handheld imagery due to image resolution.

Armando Oliu
NASA - KSC

```
*****
*
* PROGRAM PRA120 SELECTION CRITERIA
*
* -----
*
* RPT TYPE: IPR
*
* PR GROUP:
*
* MORK AREA CD:
*
* PR ELEM CD:
*
* STS NO:
*
* Starting RPT DT: 08/01/01
*
* Ending RPT DT: 09/04/01
*
* LRU or Non-LRU: B
*
* PRACA EFF CD:
*
* EICN:
*
* RPT STATUS: OP
*
* DETECTED DURING: S6444
*
* -----
*
* Sorted by DETECTED DURING, PR ELEM CD, and EICN
*
*****
```

PROBLEM REPORTING AND CORRECTIVE ACTION SYSTEM
PROBLEMS BY DETECTED DURING

*
* NO DATA FOUND ON THE DATABASE FOR THE SELECTED PARAMETERS *
*

*
* END OF REPORT *
*

[illegible]

S6444 REV: J CHG:01 (OMI)

TASK NO./SEQ. NO.	10
-------------------	----

☒ PERMANENT ☐ TEMPORARY ☐ TEMP RECYCLE

DATE/TIME: 07/02/2001 07:35:56

[illegible]

TOP/WAD No. S6444		REV/CHG/VER J 01	<input type="checkbox"/> In Family <input checked="" type="checkbox"/> Out of Family	Cause Code Org (B,D,E,G,H,L,N,O,P,Q,S,T,V) E	Cause Code Reason 10-Tech Chg 20-Proc Chg 30-Auth Error 40-Rewrite 20
Dev No. 10-01	DILS No. 89333(5)		Page 1 of 5		
First Use <input type="checkbox"/> SRB BI- <input type="checkbox"/> ET <input type="checkbox"/> GSE <input checked="" type="checkbox"/> STS-104					
Effectivity: <input type="checkbox"/> ORB /FLT <input type="checkbox"/> FRCS/POD /FLT <input type="checkbox"/> SSME /FLT					
Affected: <input type="checkbox"/> OMRS/ACOMC/OMP <input type="checkbox"/> Design Req'ts <input type="checkbox"/> Haz Step(s) <input type="checkbox"/> PPE <input checked="" type="checkbox"/> Internal Review Req.					
Contractor OPR <i>R. Seale ETM 4/27/01</i>	Contractor Test Conductor <i>Tom Ford 4/27/01</i>		Gov't Test Director or Contractor Chief TC <i>PH-H2</i>		
Contractor Test Project Engineer	Other <i>4/27/01</i>		Gov't Project Engineer		
Contractor Safety <i>R. Seale 4/27/01</i>	Other		Gov't Test Director or Contractor Chief TC		

Page Number: 10-1 Step Number: 10-3

Add Operation 11 as follows:

OPERATION 11 - IR Camera Setup

NOTE
IR CAMERA INSTALLATION(S)
MAY BE NOT PERFORMED
IF ALREADY INSTALLED (PER
PREVIOUSLY PERFORMED WAD) OR
TECHNICAL CONCERNS PRELUDE
SUCH.

WARNING

Hard hats required on the Pad when SSV is not present.

CAUTION

Exercise care to avoid dropping equipment, fasteners, etc. from RSS Roof. All tools must be tethered.

11-1 Install IR Camera at RSS Roof site as follows:

- Rotate** camera housing back cover to open position by removing bolts with flat washers (20 pl). **Retain** bolts/washers for reinstallation.
- Remove** camera housing front cover by removing fasteners (2 pl). **Reinstall** fasteners after cover removal. **Retain** cover for reinstallation after IR Camera Unit removal.
- Install** IR Camera Unit into camera housing. **Secure** IR Camera Unit in housing by locking spring pin at lower, left.

Originator (print) R. Seale	SPDMS ID T08011	Phone 1-3348	Organization ETM	Date 4/27/01	<input checked="" type="checkbox"/> Perm <input type="checkbox"/> Temp <input type="checkbox"/> Temp-Recycle
--------------------------------	--------------------	-----------------	---------------------	-----------------	---

SEE P&I CHANGE RECORD
R. Seale ETM 8/9/01



TOP/WAD Deviation

Dev No <u>10-01</u>		DILS No. <u>84333</u> (S) Page 2 of 5	
TOP/WAD No. S6444	REV/CHG/VER J 01	<input type="checkbox"/> In Family <input checked="" type="checkbox"/> Out of Family	Cause Code Org (B,D,E,G,H,L,N,O,P,Q,S,T,V) E
First Use <input type="checkbox"/> SRB BI- <input type="checkbox"/> ET <input type="checkbox"/> GSE <input checked="" type="checkbox"/> STS-104 Effectivity: <input type="checkbox"/> ORB /FLT <input type="checkbox"/> FRCS/POD /FLT <input type="checkbox"/> SSME /FLT		Cause Code Reason 10-Tech Chg 20-Proc Chg 30-Auth Error 40-Rewrite 20	
Affected: <input type="checkbox"/> OMRS/ACOMC/OMP <input type="checkbox"/> Design Req'ts <input type="checkbox"/> Haz Step(s) <input type="checkbox"/> PPE		<input checked="" type="checkbox"/> Internal Review Req.	
Contractor OPR <i>R. Seale ETM 4/27/01</i>		Contractor Test Conductor TO 27 6-28-01	
Contractor Test Project Engineer <i>Tom Ford 4/27/01</i>		Gov't OPR <i>PA #2 4-27-01</i> Gov't Project Engineer	
Contractor Safety <i>AK Sealey 28 Jun 01</i>		Gov't Test Director or Contractor Chief TC	

WARNING

Power cable is live. Care should be exercised when connecting power cable to avoid electric shock.

CAUTION

Do NOT allow opened back cover to exert undue force on cables once cables have been connected.

4. Connect:

- OTV Coaxial cable
- Pan & Tilt cable
- Controller cable
- Power cable

5. Rotate camera housing back cover into closed position. Secure back cover by installing bolts/flat washers (20 pl). Tighten bolts wrench tight.

WARNING

Isopropyl Alcohol is flammable and is a skin, eye and respiratory tract irritant that affects the central nervous system. Insure adequate ventilation, avoid inhalation of vapors and do not use near heat, sparks or open flame. Skin contact may cause redness and pain, eye contact will cause severe eye irritation and may result in permanent damage. Inhalation of vapors in high concentrations has a narcotic effect on the central nervous system. Personnel shall wear **solvex gloves** and **chemical splash goggles**. When working at eye level or above wear a **face shield** over goggles.

WS002.a 04-13-01

Originator (print) R. Seale	SPDMS ID T08011	Phone 1-3348	Organization ETM	Date 4/27/01	<input checked="" type="checkbox"/> Perm <input type="checkbox"/> Temp <input type="checkbox"/> Temp-Recycle
--------------------------------	--------------------	-----------------	---------------------	-----------------	---



TOP/WAD Deviation

TOP/WAD No. S6444		REV/CHG/VER J 01	<input type="checkbox"/> In Family <input checked="" type="checkbox"/> Out of Family	Cause Code Org (B D,E,G,H,L N,O,P,Q,S,T,V) E	Cause Code Reason 10-Tech Chg 20-Proc Chg 30-Auth Error 40-Rewrite 20
First Use <input type="checkbox"/> SRB BI- <input type="checkbox"/> ET <input type="checkbox"/> GSE <input checked="" type="checkbox"/> STS-104					
Effectivity: <input type="checkbox"/> ORB /FLT <input type="checkbox"/> FRCS/POD /FLT <input type="checkbox"/> SSME /FLT					
Affected: <input type="checkbox"/> OMRS/ACOMC/OMP <input type="checkbox"/> Design Req'ts <input type="checkbox"/> Haz Step(s) <input type="checkbox"/> PPE <input checked="" type="checkbox"/> Internal Review Req.					
Contractor OPR <i>R. Seale ETM 4/27/01</i>		Contractor Test Conductor <i>7027 6-28-01</i>		Gov't OPR <i>PH-H2 4/27/01</i>	
Contractor Test Project Engineer		Other <i>Tom Ford 4/27/01</i>		Gov't Project Engineer	
Contractor Safety <i>RL Sealey 28 Jun. 01</i>		Other		Gov't Test Director or Contractor Chief TC	
<p>6. Clean IR Camera Unit lens plate using (1) roll 8305-00-519-3144 Rymple cloth dampened with (4) ounces 6810-00-543-7915 Isopropyl Alcohol .</p> <p>7. Perform functional checkout of IR Camera Unit using local controller if required at Task Team Leader (TTL) discretion.</p> <p style="text-align: right;">S/S 7 Not Performed: <u>N/A</u></p> <p style="text-align: center;">NASA PH-H: <u>N/A</u> Date: <u>N/A</u> USA ETM: <u>N/A</u> Date: <u>N/A</u></p> <p style="text-align: center;">① NOT PERFORMED <u>8/9/01</u></p>					
Originator (print) R. Seale		SPDMS ID T08011	Phone 1-3348	Organization ETM	Date 4/27/01
				<input checked="" type="checkbox"/> Perm <input type="checkbox"/> Temp	<input type="checkbox"/> Temp-Recycle

SEE P4 I CHANGE RECORD
R. Seale ETM 8/9/01

8/9/01

Dev No. <u>10-01</u>		DILS No. <u>89333(8)</u>		Page 4 of 5
TOP/WAD No. S6444		REV/CHG/VER J 01	<input type="checkbox"/> In Family <input checked="" type="checkbox"/> Out of Family	Cause Code Org (B,D,E,G,H,L,N,O,P,Q,S,T,V) E
				Cause Code Reason 10-Tech Chg 20-Proc Chg 30-Auth Error 40-Rewrite 20
First Use <input type="checkbox"/> SRB BI- <input type="checkbox"/> ET <input type="checkbox"/> GSE <input checked="" type="checkbox"/> STS-104				
Effectivity: <input type="checkbox"/> ORB /FLT <input type="checkbox"/> FRCS/POD /FLT <input type="checkbox"/> SSME /FLT				
Affected: <input type="checkbox"/> OMRS/ACOMC/OMP <input type="checkbox"/> Design Req'ts <input type="checkbox"/> Haz Step(s) <input type="checkbox"/> PPE <input checked="" type="checkbox"/> Internal Review Req.				
Contractor OPR <i>R. Seale ETM 4/27/01</i>		Contractor Test Conductor <i>T.O. 27 628-01</i>		Gov't OPR <i>PH-A 2 4/27/01</i>
Contractor Test Project Engineer		Other <i>Tom Ford 4/27/01</i>		Gov't Project Engineer
Contractor Safety <i>AK Sealey 28 Jun 01</i>		Other		Gov't Test Director or Contractor Chief TC

SEE RFI CHANGE RECORD
 R Seale ETM 8/9/01

11-20
11-1

Install IR Camera at Camera Site 2 as follows:

- Rotate** camera housing back cover to open position by removing eight ea. bolts using Phillips screwdriver. **Retain** bolts/washers for reinstallation.
- Remove** camera housing front cover by removing securing bolt(s). **Reinstall** bolt(s) after cover removal. **Retain** cover for reinstallation after IR Camera Unit removal.
- Install** IR Camera Unit into camera housing. **Secure** IR Camera Unit in housing by tightening set screw(s) wrench tight at lower, left/right.

WARNING

Power cable is live. Care should be exercised when connecting power cable to avoid electric shock.

- Connect:**
 - OTV Coaxial cable
 - Pan & Tilt cable
 - Controller cable (2 pl)
 - Power cable
- Rotate** camera housing back cover into closed position. **Secure** back cover by installing bolts (8 pl). **Tighten** bolts using Phillips screwdriver.

Originator (print) R. Seale	SPDMS ID T08011	Phone 1-3348	Organization ETM	Date 4/27/01	<input checked="" type="checkbox"/> Perm <input type="checkbox"/> Temp <input type="checkbox"/> Temp-Recycle
--------------------------------	--------------------	-----------------	---------------------	-----------------	---

8/9/01



TOP/WAD Deviation

Dev No. <u>0-01</u>		DILS No. <u>89333(6)</u>		Page 5 of 5	
TOP/WAD No. S6444		REV/CHG/VER J 01	<input type="checkbox"/> In Family <input checked="" type="checkbox"/> Out of Family	Cause Code Org (B,D,E,G,H,L,N,O,P,Q,S,T,V) E	Cause Code Reason 13-Tech Chg 20-Proc Chg 30-Auth Error 40-Rewrite 20
First Use <input type="checkbox"/> SRB BI- <input type="checkbox"/> ET <input type="checkbox"/> GSE <input checked="" type="checkbox"/> STS-104					
Effectivity: <input type="checkbox"/> ORB /FLT <input type="checkbox"/> FRCS/POD /FLT <input type="checkbox"/> SSME /FLT					
Affected: <input type="checkbox"/> OMRS/ACOMC/OMP <input type="checkbox"/> Design Req'ts <input type="checkbox"/> Haz Step(s) <input type="checkbox"/> PPE		<input checked="" type="checkbox"/> Internal Review Req.			
Contractor OPR <i>R. Seale ETM 4/27/01</i>		Contractor Test Conductor <i>T027 6-28-01</i>		Gov't OPR <i>PH-H2 4-27-01</i>	
Contractor Test Project Engineer		Other: <i>with ETM 4/27/01</i>		Gov't Project Engineer	
Contractor Safety <i>AK Seale 28 Jun 01</i>		Other		Gov't Test Director or Contractor Chief TC	

WARNING

Isopropyl Alcohol is flammable and is a skin, eye and respiratory tract irritant that affects the central nervous system. Insure adequate ventilation, avoid inhalation of vapors and do not use near heat, sparks or open flame. Skin contact may cause redness and pain, eye contact will cause severe eye irritation and may result in permanent damage. Inhalation of vapors in high concentrations has a narcotic effect on the central nervous system. Personnel shall wear **solvex gloves** and **chemical splash goggles**. When working at eye level or above wear a **face shield** over goggles.

WS002.a 04-13-01

6. **Clean** IR Camera Unit lens plate using (1) roll 8305-00-519-3144 Rymple cloth dampened with (4) ounces 6810-00-543-7915 Isopropyl Alcohol.
7. **Perform** functional checkout of IR Camera Unit using local controller if required at Task Team Leader (TTL) discretion.

S/S 7 Not Performed: N/ANASA PH-H: N/A Date: N/AUSA ETM: N/A Date: N/A

① NOT PERFORMED

8/9/01

Reason: Establish operational controls for installation of the IR Camera units on the RSS Roof and Camera Site 2.

Originator (print) R. Seale	SPDMS ID T08011	Phone 1-3348	Organization ETM	Date 4/27/01	<input checked="" type="checkbox"/> Perm <input type="checkbox"/> Temp <input type="checkbox"/> Temp-Recycle
--------------------------------	--------------------	-----------------	---------------------	-----------------	---

8/9/01

① R. Seale ETM 8/9/01
SEE P&I CHANGE RECORD

[illegible]

KSC FORM 4-470 (C/G 07/93)



TOP/WAD Deviation

TOP/WAD No. S6444		REV/CHG/VER J01	<input type="checkbox"/> In Family <input checked="" type="checkbox"/> Out of Family	Cause Code Org (B,D,E,G,H,L,N,O,P,Q,S,T,V) E	Cause Code Reason 10-Tech Chg 20-Proc Chg 30-Auth Error 40-Rewrite 30
First Use <input type="checkbox"/> SRB BI- <input type="checkbox"/> ET		<input type="checkbox"/> GSE <input checked="" type="checkbox"/> STS-100			
Effectivity: <input type="checkbox"/> ORB /FLT		<input type="checkbox"/> FRCS/POD /FLT		<input type="checkbox"/> SSME /FLT	
Affected: <input checked="" type="checkbox"/> OMRS/ACOMC/OMP		<input type="checkbox"/> Design Req'ts		<input type="checkbox"/> PPE	
<input checked="" type="checkbox"/> Internal Review Req.					
Contractor OER <i>R Seale ETM 4/5/01</i>		Contractor Test Conductor <i>Jim Taylor 4-9-01</i>		Gov't OPR <i>PAH2</i>	
Contractor Test Project Engineer <i>Paula Wollen 4/9/01</i>		Other <i>Mark Wollen 4/5/01</i>		Gov't Project Engineer <i>NTS</i>	
Contractor Safety		Other		Gov't Test Director or Contractor Chief TC <i>Mark Wollen 4/9/01</i>	
<p>Page Number: 50-4 Step Number: 50-8</p> <p>Add following (one line below end of step text):</p> <p>OMRS S00FB0.350-1</p>					
Originator (print) R Seale		SPDMS ID T08011	Phone 1-3348	Organization ETM	Date 4/5/01
				<input checked="" type="checkbox"/> Perm <input type="checkbox"/> Temp <input type="checkbox"/> Temp-Recycle	



TOP/WAD Deviation

Dev No. <u>50-01</u>		DILS No. <u>87031</u> (S)		Page 2 of 4
TOP/WAD No. S6444		REV/CHG/VER J01	<input type="checkbox"/> In Family <input checked="" type="checkbox"/> Out of Family	Cause Code Org (B,D,E,G,H,L,N,O,P,Q,S,T,V) E
				Cause Code Reason 10-Tech Chg 20-Proc Chg 30-Auth Error 40-Rewrite 30
First Use <input type="checkbox"/> SRB BI- <input type="checkbox"/> ET <input type="checkbox"/> GSE <input checked="" type="checkbox"/> STS-100				
Effectivity: <input type="checkbox"/> ORB /FLT <input type="checkbox"/> FRCS/POD /FLT <input type="checkbox"/> SSME /FLT				
Affected: <input checked="" type="checkbox"/> OMRS/ACOMC/OMP <input type="checkbox"/> Design Req'ts <input type="checkbox"/> Haz Step(s) <input type="checkbox"/> PPE		<input checked="" type="checkbox"/> Internal Review Req.		
Contractor DPR <i>R. Seale ETM 4/5/01</i>		Contractor Test Conductor <i>Jim Taylor 4-9-01</i>		Gov't DPR <i>PH-HZ</i>
Contractor Test Project Engineer <i>Mark Wollam 4/5/01</i>		Gov't Project Engineer <i>4-6-01</i>		
Contractor Safety		Gov't Test Director, or Contractor Chief, TC <i>4/9/01</i>		

Page Number: 50-5 Step Number: 50-10

Add steps 50-10.1 with preceding Note and 50-10.2 as follows:

NOTE

Excessive vapors are defined as being more severe than those described in NSTS 08303 (LI) NSTS PROGRAM ICE/DEBRIS INSPECTION CRITERIA or NSTS 16007 (LI) NSTS PROGRAM LAUNCH COMMIT CRITERIA - HAZARDOUS GAS SUBSYSTEM.

50-10.1 CTIF CVM1 222
CVM2

From start of LO₂ / LH₂ loading until Prepressurization (LO₂ at T-2M55s and LH₂ at T-1M57s):

1. Monitor following ET-Orbiter MPS areas for leakage:
 - LO₂ Feedline (portion external to the Intertank)
 - LH₂ Feedline
 - LH₂ Recirculation Line
 - LH₂ Aft Dome Manhole Cover(s)
 - ET-Orbiter LO₂ / LH₂ Umbilical Disconnects
 - LH₂ T-0 Umbilical
 - LO₂ T-0 Umbilical
2. Verify no visible cryogenic liquid of excessive vapors.

OMRS (general) S00FB0.360-1


ETM ME
08 Date 8-10-01

Not Performed: N/A

Originator (print) R. Seale	SPDMS ID T08011	Phone 1-3348	Organization ETM	Date 4/5/01	<input checked="" type="checkbox"/> Perm <input type="checkbox"/> Temp <input type="checkbox"/> Temp-Recycle
--------------------------------	--------------------	-----------------	---------------------	----------------	---



TOP/WAD Deviation

Dev No. <u>50-01</u>		DILS No. <u>87031</u> (5)		Page 3 of 4	
TOP/WAD No. S6444		REV/CHG/VER J01		<input type="checkbox"/> In Family <input checked="" type="checkbox"/> Out of Family	
		Cause Code Org (B,D,E,G,H,L,N,O,P,Q,S,T,V) E		Cause Code Reason 10-Tech Chg 20-Proc Chg 30-Auth Error 40-Rewrite 30	
First Use <input type="checkbox"/> SRB BI- <input type="checkbox"/> ET <input type="checkbox"/> GSE <input checked="" type="checkbox"/> STS-100					
Effectivity <input type="checkbox"/> ORB /FLT <input type="checkbox"/> FRCS/POD /FLT <input type="checkbox"/> SSME /FLT					
Affected: <input checked="" type="checkbox"/> OMRS/ACOMC/OMP <input type="checkbox"/> Design Req'ts <input type="checkbox"/> Haz Step(s) <input type="checkbox"/> PPE				<input checked="" type="checkbox"/> Internal Review Req.	
Contractor OPR <i>R. Seale ETM 4/5/01</i>		Contractor Test Conductor <i>Jim Tabor 4-9-01</i>		Gov't OPR <i>PH-HZ 4-6-01</i>	
Contractor Test Project Engineer <i>Mark Wollam 4/5/01</i>		Other <i>Mark Wollam 4/5/01</i>		Gov't Project Engineer	
Contractor Safety		Other		Gov't Test Director or Contractor Chief TC <i>Stephen J. Payne 4/9/01</i>	
<p>50-10.2 CTIF CVM1 222 CVM2</p> <p>Monitor and videotape record following ET TPS surface areas and GO₂ Vent Area during LO₂ / LH₂ loading through Prepressurization (LO₂ at T-2M55s and LH₂ at T-1M57s):</p> <ul style="list-style-type: none">• LH₂ Aft Dome• LH₂ Barrel• Intertank (external)• LO₂ Tank• GO₂ Vent Area• Protuberances <p>OMRS (general) S00FB0.005-1</p> <p>ETM  Date <u>8-10-01</u></p> <p>Not Performed: <u>N/A</u></p>					
Originator (print) R Seale		SPDMS ID T08011		Phone 1-3348	
		Organization ETM		Date 4/5/01	
				<input checked="" type="checkbox"/> Perm <input type="checkbox"/> Temp <input type="checkbox"/> Temp-Recycle	

[illegible]

KSC FORM 4-470 (C/G 07/93)



TOP/WAD Deviation

Dev No. <u>60-01</u>		DILS No. <u>87032</u> (S)		Page 1 of 1	
TOP/WAD No. S6444		REV/CHG/VER J01		<input type="checkbox"/> In Family <input checked="" type="checkbox"/> Out of Family	
		Cause Code Org (B,D,E,G,H,L,N,O,P,Q,S,T,V) E		Cause Code Reason 10-Tech Chg 20-Proc Chg 30-Auth Error 40-Rewrite 30	
First Use <input type="checkbox"/> SRB BI- <input type="checkbox"/> ET <input type="checkbox"/> GSE <input checked="" type="checkbox"/> STS-100		Effectivity: <input type="checkbox"/> ORB /FLT <input type="checkbox"/> FRCS/POD /FLT <input type="checkbox"/> SSME /FLT			
Affected: <input checked="" type="checkbox"/> OMRS/ACOMC/OMP <input type="checkbox"/> Design Req'ts <input type="checkbox"/> Haz Step(s) <input type="checkbox"/> PPE				<input checked="" type="checkbox"/> Internal Review Req.	
Contractor QBR <i>R. Seale Firm 4/5/01</i>		Contractor Test Conductor <i>ME TO Jim 4-9-01</i>		Gov't QBR <i>PH-112 Robert F. 4-6-01</i>	
Contractor Test Project Engineer <i>Paul C. 4/9/01</i>		Other <i>Mark Nollan 4/5/01</i>		Gov't Project Engineer	
Contractor Safety		Other		Gov't Test Director or Contractor Chief TC <i>4/9/01</i>	
<p>Page Number: 60-1 Step Number: 60-1</p> <p>Delete OMRS S00FB0.005-1 and S00L00.150-1 from Note preceding step 60-1: "Noted ... operation."</p> <p>Page Number: 60-6 Step Number: 60-12</p> <p>Delete OMRSD S00FB0.005-1 and OMRSD S00L00.150-1 from step 60-12.</p> <p>Reason: These OMRSD's have been moved to Operation 50.</p>					
Originator (print) R. Seale		SPDMS ID T08011		Phone 1-3348	
Organization ETM		Date 4/5/01		<input checked="" type="checkbox"/> Perm <input type="checkbox"/> Temp <input type="checkbox"/> Temp-Recycle	

[illegible]

KSC FORM 4-470 (C/G 07/93)



TOP/WAD Deviation

Dev No. <u>70-01</u>		DILS No. <u>87033</u> (S)		Page 1 of 1	
TOP/WAD No. S6444		REV/CHG/VER J01		<input type="checkbox"/> In Family <input checked="" type="checkbox"/> Out of Family	
		Cause Code Org (B,D,E,G,H,I,N,O,P,Q,S,T,V) E		Cause Code Reason 10-Tech Chg 20-Proc Chg 30-Auth Error 40-Rewrite 30	
First Use <input type="checkbox"/> SRB BI- <input type="checkbox"/> ET <input type="checkbox"/> GSE <input checked="" type="checkbox"/> STS-100					
Effectivity: <input type="checkbox"/> ORB /FLT <input type="checkbox"/> FRCS/POD /FLT <input type="checkbox"/> SSME /FLT					
Affected: <input checked="" type="checkbox"/> OMRS/ACOMC/OMP <input type="checkbox"/> Design Req'ts <input type="checkbox"/> Haz Step(s) <input type="checkbox"/> PPE <input checked="" type="checkbox"/> Internal Review Req.					
Contractor OPR <i>R. Seale ETM 4/5/01</i>		Contractor Test Conductor <i>Jim J. for 4-9-01</i>		Gov't OPR <i>PH-A12 4-6-01</i>	
Contractor Test Project Engineer <i>Carl Cherry Conway 4/9/01</i>		Other <i>Mark Wollam 4/5/01</i>		Gov't Project Engineer	
Contractor Safety		Other:		Gov't Test Director or Contractor Chief TC <i>Stephen J. Payne 4/9/01</i>	
<p>Page Number: 70-1 Step Number: 70-1</p> <p>Delete OMRS S00FB0.005-1 and S00FB0.360-1 from Note preceding step 70-1: "Noted ... operation." ①</p> <p>Page Number: 70-6 Step Number: 70-12</p> <p>Delete OMRSD S00FB0.005-1 and OMRSD S00FB0.360-1 ^{and} from step 70-12. ①</p> <p>Reason: These OMRSD's are satisfied via Operation 50.</p>					
Originator (print) R. Seale		SPDMS ID T08011		Phone 1-3348	
		Organization ETM		Date 4/5/01	
				<input checked="" type="checkbox"/> Perm <input type="checkbox"/> Temp <input type="checkbox"/> Temp-Recycle	

[illegible]

TASK NO./SEQ. NO. 130

☒ PERMANENT ☐ TEMPORARY ☐ TEMP RECYCLE

DATE/TIME: 04/10/2001 05:39:17

DEV NO.	SEQ/ STEP	EFFECTIVITY	QC/ PP&C	DATE	REMARKS
------------	--------------	-------------	-------------	------	---------

130-01

SEQ/
STEP

130 2

EFFECTIVITY

QC/
PF&C

✖

DATE _____

2001-04-09

REMARKS



TOP/WAD Deviation

TOP/WAD No. S6444		REV/CHG/VER J01	<input type="checkbox"/> In Family <input checked="" type="checkbox"/> Out of Family	Cause Code Org (B,D,E,G,H,L,N,O,P,Q,S,T,V) E	Cause Code Reason 10-Tech Chg 20-Proc Chg 30-Auth Error 40-Rewrite 30
First Use <input type="checkbox"/> SRB BI- <input type="checkbox"/> ET <input type="checkbox"/> GSE <input checked="" type="checkbox"/> STS-100 Effectivity: <input type="checkbox"/> ORB /FLT <input type="checkbox"/> FRCS/POD /FLT <input type="checkbox"/> SSME /FLT		Affected: <input checked="" type="checkbox"/> OMRS/ACOMC/OMP <input type="checkbox"/> Design Req'ts <input type="checkbox"/> Haz Step(s) <input type="checkbox"/> PPE <input checked="" type="checkbox"/> Internal Review Req.			
Contractor QPR <i>R. Seale ETM 4/5/01</i>		Contractor Test Conductor <i>Jim Taylor 4/9/01</i>		Gov't QPR <i>PH-H2 4-6-01</i>	
Contractor Test Project Engineer <i>Paul Riley company 4/9/01</i>		Other <i>Mark Wollan 4/5/01</i>		Gov't Project Engineer	
Contractor Safety		Other		Gov't Test Director or Contractor Chief TC <i>Stephen Payne 4/9/01</i>	
<p>Page Number: 130-2 Step Number: 130-2</p> <p>Add following Note prior to step 130-2:</p> <div style="border: 1px solid black; padding: 10px; text-align: center;"> <p>NOTE</p> <p>Post Launch Walkdown must be performed prior to washdown and Pad being opened for normal work.</p> </div> <p>Reason: Ensure text of operational instructions complies with OMRS S00U00.010-1.</p>					
Originator (print) R. Seale	SPDMS ID T08011	Phone 1-3348	Organization ETM	Date 4/5/01	<input checked="" type="checkbox"/> Perm <input type="checkbox"/> Temp <input type="checkbox"/> Temp-Recycle

[illegible]

XSC FORM 4-470 (C/G 07/93)



TOP/WAD Deviation

Dev No. <u>140-01</u>		DILS No. <u>87035</u> (S)		Page 1 of 1	
TOP/WAD No. S6444		REV/CHG/VER J01		<input type="checkbox"/> In Family <input checked="" type="checkbox"/> Out of Family	
				Cause Code Org (B,D,E,G,H,L,N,O,P,Q,S,T,V) E	
				Cause Code Reason 10-Tech Chg 20-Proc Chg 30-Auth Error 40-Rewrite 30	
First Use <input type="checkbox"/> SRB BI- <input type="checkbox"/> ET <input type="checkbox"/> GSE <input checked="" type="checkbox"/> STS-100					
Effectivity: <input type="checkbox"/> ORB /FLT <input type="checkbox"/> FRCS/POD /FLT <input type="checkbox"/> SSME /FLT					
Affected: <input checked="" type="checkbox"/> OMRS/ACOMC/OMP <input type="checkbox"/> Design Req'ts <input type="checkbox"/> Haz Step(s) <input type="checkbox"/> PPE				<input checked="" type="checkbox"/> Internal Review Req.	
Contractor QBR <i>R. Seale 4/5/01</i>		Contractor Test Conductor <i>Jim S. 4-9-01</i>		Gov't QBR <i>PH-112 4-6-01</i>	
Contractor Test Project Engineer <i>Mark Wollan 4/5/01</i>		Other <i>Mark Wollan 4/5/01</i>		Gov't Project Engineer <i>NTS 4/9/01</i>	
Contractor Safety		Other		Gov't Test Director or Contractor Chief TC <i>NTS 4/9/01</i>	

Page Number: 140-1 Step Number: 140-1

Add following Note and change step 140-1 to read as follows:

NOTE

Analysis of Pad Debris Inspection Results determines priority for film review. All critical film (as determined by the Debris Team) must be reviewed as soon as possible after launch and no later than 36 hours prior to entry (of the Orbiter into the earth's atmosphere).

140-1 Review and analyze all engineering launch (and flight film) to:

- Identify any debris damage to the SSV
- Identify flight vehicle or ground system damage that could affect Orbiter flight operations or future SSV launches.

OMRSD S00U00.011-1 *4-5-01*ETM: *R. Seale*Date *4/5/01*

Reason: Ensure text of operational instructions complies with the OMRS S00U00.011-1.

Originator (print) R. Seale	SPDMS ID T08011	Phone 1-3348	Organization ETM	Date 4/5/01	<input checked="" type="checkbox"/> Perm <input type="checkbox"/> Temp <input type="checkbox"/> Temp-Recycle
--------------------------------	--------------------	-----------------	---------------------	----------------	---



TOP/WAD Deviation

Dev No. <u>140-02</u>		DILS No. <u>89334 (3)</u>		Page 1 of 5
TOP/WAD No. S6444		REV/CHG/VER J 01	<input type="checkbox"/> In Family <input checked="" type="checkbox"/> Out of Family	Cause Code Org (B,D,E,G,H,L,N,O,P,Q,S,T,V) E
				Cause Code Reason 10-Tech Chg 20-Proc Chg 30-Auth Error 40-Rewrite 20
First Use <input type="checkbox"/> SRB B:- <input type="checkbox"/> ET <input type="checkbox"/> GSE <input checked="" type="checkbox"/> STS-104		Effectivity: <input type="checkbox"/> ORB /FLT <input type="checkbox"/> FRCS/POD /FLT <input type="checkbox"/> SSME /FLT		
Affected: <input type="checkbox"/> OMRS/ACOMC/OMP <input type="checkbox"/> Design Req'ts <input type="checkbox"/> Haz Step(s) <input type="checkbox"/> PPE		<input checked="" type="checkbox"/> Internal Review Req.		
Contractor OPR <i>R. Seale Etm 6/27/01</i>		Contractor Test Conductor <i>T027 6-28-01</i>		Gov't OPR <i>PH-112</i>
Contractor Test Project Engineer		Other <i>Other</i>		Gov't Project Engineer
Contractor Safety <i>R. Seale Etm 28 Jun. 01</i>		Other <i>Check Richards 6-27-01</i>		Gov't Test Director or Contractor Chief TC

Page Number: 140-1 Step Number: 140-2

Add Operation 141 as follows:

NOTE
IF CAMERA REMOVAL
DURING LAUNCH SEQUENCE,
REINSTALLATION SEQUENCE,

OPERATION 141 - IR Camera Removal

WARNING

Hard hats required on the Pad when SSV is not present.

CAUTION

Exercise care to avoid dropping equipment, fasteners, etc. from RSS Roof. All tools must be tethered.

Remove IR Camera from RSS Roof site as follows:

- Remove** fasteners (2 pl) from camera housing front. **Retain** fasteners for reinstallation when front cover is installed.
- Install** camera housing front cover using previously removed fasteners (2 pl). **Tighten** fasteners (2 pl) wrench tight.

Originator (print) R. Seale	SPDMS ID T08011	Phone 1-3348	Organization ETM	Date 6/27/01	<input checked="" type="checkbox"/> Perm <input type="checkbox"/> Temp <input type="checkbox"/> Temp-Recycle
--------------------------------	--------------------	-----------------	---------------------	-----------------	---

SEE PAT CHANGE RECORD
R. Seale Etm 8/14/01

141-1
11-1



TOP/WAD Deviation

Dev No. <u>140 02</u>		DILS No. <u>89334(9)</u>		Page 2 of 5
TOP/WAD No. S6444	REV/CHG/VER J 01	<input type="checkbox"/> In Family <input checked="" type="checkbox"/> Out of Family	Cause Code Org (B,D,E,G,H,L,N,O,P,Q,S,T,V) E	Cause Code Reason 10-Tech Chg 20-Proc Chg 30-Auth Error 40-Rewrite 20
First Use <input type="checkbox"/> SRB B:- <input type="checkbox"/> ET <input type="checkbox"/> GSE <input checked="" type="checkbox"/> STS-104				
Effectivity: <input type="checkbox"/> ORB /FLT <input type="checkbox"/> FRCS/POD /FLT <input type="checkbox"/> SSME /FLT				
Affected: <input type="checkbox"/> OMRS/ACOMC/OMP <input type="checkbox"/> Design Req'ts <input type="checkbox"/> Haz Step(s) <input type="checkbox"/> PPE <input checked="" type="checkbox"/> Internal Review Req.				
Contractor OPR <u>R. Seale ETM 6/27/01</u>	Contractor Test Conductor <u>TO 27 6-28-01</u>		Gov't OPR <u>PH-H2 6-28-01</u>	
Contractor Test Project Engineer	Other		Gov't Project Engineer	
Contractor Safety <u>R. Seale 28 Jun. 01</u>	Other <u>SE Check 6-27-01</u>		Gov't Test Director or Contractor Chief TC	

WARNING

Power cable is live. Care should be exercised when disconnecting power cable to avoid electric shock.

CAUTION

Do NOT allow back cover to exert undue force on cables when opening/rotating back over.

3. **Rotate** camera housing back cover to open position by removing bolts with flat washers (20 pl). **Retain** bolts/washers for reinstallation.
4. **Disconnect:**
 - Power cable
 - Pan & Tilt cable
 - Controller cable
 - OTV Coaxial cable
5. **Unlock** spring pin at lower, left to release IR Camera Unit in camera housing. **Remove** IR Camera Unit from camera housing by carefully sliding it out the back opening of the camera housing. **Support** IR Camera Unit during removal.
6. **Rotate** camera housing back cover into closed position. Do not pinch cables. **Secure** back cover by reinstalling bolts/flat washers (20 pl). **Tighten** bolts wrench tight.

Originator (print) R. Seale	SPDMS ID T08011	Phone 1-3348	Organization ETM	Date 6/27/01	<input checked="" type="checkbox"/> Perm <input type="checkbox"/> Temp <input type="checkbox"/> Temp-Recycle
--------------------------------	--------------------	-----------------	---------------------	-----------------	---

6/30/01



TOP/WAD Deviation

Dev No. <u>140-02</u>		DILS No. <u>89334(5)</u>		Page 3 of 5
TOP/WAD No. S6444	REV/CHG/VER J 01	<input type="checkbox"/> In Family <input checked="" type="checkbox"/> Out of Family	Cause Code Org (B,D,E,G,H,L,N,O,P,Q,S,T,V) E	Cause Code Reason 10-Tech Chg 20-Proc Chg 30-Auth Error 40-Rewrite 20
First Use <input type="checkbox"/> SRB BI- <input type="checkbox"/> ET <input type="checkbox"/> GSE <input checked="" type="checkbox"/> STS-104				
Effectivity: <input type="checkbox"/> ORB /FLT <input type="checkbox"/> FRCS/POD /FLT <input type="checkbox"/> SSME /FLT				
Affected: <input type="checkbox"/> OMRS/ACOMC/OMP <input type="checkbox"/> Design Req'ts <input type="checkbox"/> Haz Step(s) <input type="checkbox"/> PPE <input checked="" type="checkbox"/> Internal Review Req.				
Contractor OPR <u>R. Seale ETM 6/27/01</u>	Contractor Test Conductor <u>TO 27 6-28-01</u>	Gov't OPR <u>[Signature] PH-HZ 6-28-01</u>		
Contractor Test Project Engineer	Other	Gov't Project Engineer		
Contractor Safety <u>R. Seale 28 Jun. 01</u>	Other <u>[Signature] 6-27-01</u>	Gov't Test Director or Contractor Chief TC		

WARNING

Isopropyl Alcohol is flammable and is a skin, eye and respiratory tract irritant that affects the central nervous system. Insure adequate ventilation, avoid inhalation of vapors and do not use near heat, sparks or open flame. Skin contact may cause redness and pain, eye contact will cause severe eye irritation and may result in permanent damage. Inhalation of vapors in high concentrations has a narcotic effect on the central nervous system. Personnel shall wear solvex gloves and chemical splash goggles. When working at eye level or above wear a face shield over goggles.

WS002.a 04-13-01

7. Clean IR Camera Unit lens plate using (1) roll 8305-00-519-3144 Rymple cloth dampened with (4) ounces 6810-00-543-7915 Isopropyl Alcohol.
8. Route IR Camera Unit to VAB 3K1 for refurb/checkout.

NASA PH-H: [Signature] Date: 8/31/01
USA ETM: Tom Ford Date: 8-15-01

NOT PERFORMED N/A

Originator (print) R. Seale	SPDMS ID T08011	Phone 1-3348	Organization ETM	Date 6/27/01	<input checked="" type="checkbox"/> Perm <input type="checkbox"/> Temp <input type="checkbox"/> Temp-Recycle
---------------------------------------	---------------------------	------------------------	----------------------------	------------------------	---

0-5444 TOP/WAD Deviation
 A. Seale ETM 6/27/01



TOP/WAD Deviation

Dev No. <u>140-02</u>		DILS No. <u>89334(9)</u>		Page 4 of 5	
TOP/WAD No. S6444		REV/CHG/VER J 01		<input type="checkbox"/> In Family <input checked="" type="checkbox"/> Out of Family	
		Cause Code Org (B,D,E,G,H,L,N,O,P,Q,S,T,V) E		Cause Code Reason 10-Tech Chg 20-Proc Chg 30-Auth Error 40-Rewrite 20	
First Use <input type="checkbox"/> SRB BI- <input type="checkbox"/> ET <input type="checkbox"/> GSE <input checked="" type="checkbox"/> STS-104		Effectivity: <input type="checkbox"/> ORB /FLT <input type="checkbox"/> FRCS/POD /FLT <input type="checkbox"/> SSME /FLT			
Affected: <input type="checkbox"/> OMRS/ACOMC/OMP <input type="checkbox"/> Design Req'ts <input type="checkbox"/> Haz Step(s) <input type="checkbox"/> PPE				<input checked="" type="checkbox"/> Internal Review Req.	
Contractor OPR <i>R. Seale ETM 6/27/01</i>		Contractor Test Conductor <i>T027 6-28-01</i>		Gov't OPR <i>PH-AL 6-28-01</i>	
Contractor Test Project Engineer		Other		Gov't Project Engineer	
Contractor Safety <i>R. Seale 28 Jun. 01</i>		Other <i>SE Check 6-27-01</i>		Gov't Test Director or Contractor Chief TC	
<p>141-2 111</p> <p>Remove IR Camera from Camera Site 2 as follows:</p> <ol style="list-style-type: none">1. Remove bolt(s) from camera housing front. Retain bolt(s) for reinstallation when front cover is installed.2. Install camera housing front cover using previously removed bolt(s). Torque bolt(s) wrench tight. <div style="border: 1px solid black; padding: 5px; text-align: center;">WARNING Power cable is live. Care should be exercised when disconnecting power cable to avoid electric shock.</div> <div style="border: 1px solid black; padding: 5px; text-align: center;">CAUTION Do NOT allow back cover to exert undue force on cables when opening/rotating back over.</div> <ol style="list-style-type: none">3. Loosen screws (8 pl) securing camera housing back cover using Phillips screwdriver. Rotate camera housing back cover to open position. Retain bolts/washers for reinstallation.4. Disconnect:<ul style="list-style-type: none">• Power cable• Pan & Tilt cable• Controller cable (2 pl)• OTV Coaxial cable5. Unscrew set screw(s) at lower, left/right to release IR Camera Unit in camera housing. Remove IR Camera Unit from camera housing by carefully sliding it out the back opening of the camera housing. Support IR Camera Unit during removal.					
Originator (print) R. Seale		SPDMS ID T08011		Phone 1-3348	
		Organization ETM		Date 6/27/01	
				<input checked="" type="checkbox"/> Perm <input type="checkbox"/> Temp <input type="checkbox"/> Temp-Recycle	

SEE P & I CHANGE RECORD
D. Seale ETM 8/14/01

ET
01

8. b. k. a



TOP/WAD Deviation

TOP/WAD No. S6444		REV/CHG/VER J 01	<input type="checkbox"/> In Family <input checked="" type="checkbox"/> Out of Family	Cause Code Org (B,D,E,G,H,L,N,O,P,Q,S,T,V) E	Cause Code Reason 10-Tech Chg 20-Proc Chg 30-Auth Error 40-Rewrite 20
First: Use <input type="checkbox"/> SRB BI- <input type="checkbox"/> ET <input type="checkbox"/> GSE <input checked="" type="checkbox"/> STS-104		Effectivity: <input type="checkbox"/> ORB /FLT <input type="checkbox"/> FRCS/POD /FLT <input type="checkbox"/> SSME /FLT			
Affected: <input type="checkbox"/> OMRS/ACOMC/OMP <input type="checkbox"/> Design Req'ts <input type="checkbox"/> Haz Step(s) <input type="checkbox"/> PPE		<input checked="" type="checkbox"/> Internal Review Req.			
Contractor OPR <i>R. Seale ETM 6/27/01</i>		Contractor Test Conductor <i>To 27 6-28-01</i>		Gov't OPR <i>PA-H/L</i>	
Contractor Test Project Engineer		Other		Gov't Project Engineer <i>6-28-01</i>	
Contractor Safety <i>H. Sealey 28 Jun. 01</i>		Other <i>Richards 58 Check 6-27-01</i>		Gov't Test Director or Contractor Chief TC	

6. Coat camera housing back cover O-ring with a single coat of (1) tube / jar 6505-00-133-8025 Petroleum Jelly, Vaseline (or equivalent).
5. Rotate camera housing back cover into closed position. Do not pinch cables. **Secure** back cover by installing screws (8 pl). **Tighten** screws wrench tight using Phillips screwdriver.

WARNING

Isopropyl Alcohol is flammable and is a skin, eye and respiratory tract irritant that affects the central nervous system. Insure adequate ventilation, avoid inhalation of vapors and do not use near heat, sparks or open flame. Skin contact may cause redness and pain, eye contact will cause severe eye irritation and may result in permanent damage. Inhalation of vapors in high concentrations has a narcotic effect on the central nervous system. Personnel shall wear **solvex gloves** and **chemical splash goggles**. When working at eye level or above wear a **face shield** over goggles.

WS002.a 04-13-01

7. Clean IR Camera Unit lens plate using (1) roll 8305-00-519-3144 Rymple cloth dampened with (4) ounces 6810-00-543-7915 Isopropyl Alcohol.
8. Route IR Camera Unit to VAB 3K1 for refurb/checkout.

NASA PH-H: *[Signature]* Date: *6/28/01*

USA ETM: *Tom Fox* Date: *6-15-01*

Not PERFORMED *N/A*

Reason: Establish operational controls for removal of IR Camera units from the RSS Roof and Camera Site 2.

Originator: (print) R. Seale	SPDMS ID T08011	Phone 1-3348	Organization ETM	Date 6/27/01	<input checked="" type="checkbox"/> Perm <input type="checkbox"/> Temp <input type="checkbox"/> Temp-Recycle
---------------------------------	--------------------	-----------------	---------------------	-----------------	---

© See PH-H CRW-22 RECORD
 R. Seale ETM 6/27/01

[illegible]

TASK NO./SEQ. NO. 150

DATE/TIME: 04/10/2001 05:39:54

150-01	150 2	*	2001-04-09
--------	-------	---	------------



TOP/WAD Deviation

Dev No. <u>150-01</u>		DILS No. <u>87036^(S)</u>		Page 1 of 1	
TOP/WAD No. S6444		REV/CHG/VER J01		<input type="checkbox"/> In Family <input checked="" type="checkbox"/> Out of Family	
		Cause Code Org (B,D,E,G,H,L,N,O,P,Q,S,T,V) E		Cause Code Reason 10-Tech Chg 20-Proc Chg 30-Auth Error 40-Rewrite 30	
First Use <input type="checkbox"/> SRB BI- <input type="checkbox"/> ET <input type="checkbox"/> GSE <input checked="" type="checkbox"/> STS-100					
Effectivity: <input type="checkbox"/> ORB /FLT <input type="checkbox"/> FRCS/POD /FLT <input type="checkbox"/> SSME /FLT					
Affected: <input checked="" type="checkbox"/> OMRS/ACOMC/OMP <input type="checkbox"/> Design Req'ts <input type="checkbox"/> Haz Step(s) <input type="checkbox"/> PPE				<input checked="" type="checkbox"/> Internal Review Req.	
Contractor OPR <i>R. Seale</i> <i>4/5/01</i>		Contractor Test Conductor <i>Jim Taylor</i> <i>4/9/01</i>		Gov't OPR <i>PH-HZ</i> <i>4-6-01</i>	
Contractor Test Project Engineer <i>Kelly Kelly Connolly</i> <i>4/9/01</i>		Other <i>Mark Wollan</i> <i>4/5/01</i>		Gov't Project Engineer	
Contractor Safety		Other		Gov't Test Director or Contractor Chief TC <i>Stephen Payne</i> <i>4/9/01</i>	
<p>Page Number: 140-1 (s/b 150-1) Step Number: 150-2</p> <p>Delete following from step 150-2:</p> <p>"OMRSD S00U00.011-1"</p> <p>Reason: OMRS S00U00.011-1 pertains to Film Review (Operation 140).</p>					
Originator (print) R. Seale		SPDMS ID T08011		Phone 1-3348	
		Organization ETM		Date 4/5/01	
				<input checked="" type="checkbox"/> Perm <input type="checkbox"/> Temp <input type="checkbox"/> Temp-Recycle	

NO./REVISION

56444 J41

EFFECTIVITY

STS-105 RUN 2

PAGE	SEQ/OP-STEP	CHANGE	APPROVAL QE/ENG
DEV 10-01 PG 1/5	11-1	ADDED NOTE AS NOT PERFORMED QUALIFIER	R. Spaulding ETM 8/9/01
DEV 10-01 PG 3/5	11-1	ADDED NOT PERFORMED BUY	R. Spaulding ETM 8/9/01
DEV 10-01 PG 4/5	11-2	CORRECTED STEP NUMBER WAS: 11-1 IS: 11-2	R. Spaulding ETM 8/9/01
DEV 10-01 PG 5/5	11-2	ADDED NOT PERFORMED BUY	R. Spaulding ETM 8/9/01
DEV 140-02 PG 1/5	141-1	CORRECTED STEP NUMBER WAS: 11-1 IS: 141-1	R. Spaulding ETM 8/14/01
DEV 140-02 PG 4/5	141-2	CORRECTED STEP NUMBER WAS: 11-1 IS: 141-2	R. Spaulding ETM 8/14/01
80-7	80-2	ADDED NOTE (FOR QUALIFIER) AND NOT PERFORMED BUY FOR S/S 1	R. Spaulding ETM 8/16/01
141-1 DEV 140-02 PG 1/5	PG 1/5	ADDED NOTE FOR NOT PERFORMED QUALIFIER	R. Spaulding ETM 8/16/01
141-2 DEV 140-02 PG 3/5	PG 3/5	ADDED NOT PERFORMED	R. Spaulding ETM 8/16/01
141-2 DEV 140-02 PG 5/5	PG 5/5	ADDED NOT PERFORMED	R. Spaulding ETM 8/16/01